

# SURVEY & REMONUMENTATION

OCT 24 1994

COMMISSION

## OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 OCT -7 PM 12:33

*D. J. J. J. J.*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI

For corners in

Ottawa

(County)

Located In:

Corner Code #

1. Public Land Survey T 6N R 14W C-3, NW 1/4 COR  
T R Sec. 8, Blendon  
T R  
T R
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, Randal D. Feenstra, in a field survey on May 9, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

### A. Description of original monument and accessories and/or subsequent restoration:

L.O. (1832)	Liber 1, Page 495 (1972)	Liber 2, page 585 (1974)	Liber 5, Page 1 (1982)
Hemlock N86°E 9.2	1" Pipe in Mon. Box	1" Pipe in Mon. Box	C.I.M.
Hemlock S47°W 6.6	PP NW 47.64	PP NW 46.85	PP NW 46.84
POST	PP NE 86.85	PP NE 86.50	PP NE 86.50
Samuel Marrs	St. Sign SE 45.3	PP SE 94.52	PP SE 95.34
		CL St. Sign SE 45.33	9" Birch SW 76.76

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found: Cast Iron Monument - accepted as a careful and faithful perpetuation of the position of the original corner.

Found Witnesses:

Nail and tag SE side PP N45°W 46.89  
Nail NE side PP N45°W 47.64

P.A. 345 OTTAWA COUNTY

PEER APPROVED 9/22/94

*Gordon D. Hedwood*

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3 Cast Iron Mon. in Mon. Box		
O.C. Remon. Nail & tag SW side PP	N45°W	47.64
O.C. Remon. Nail & tag NW side PP	N55°E	86.45
O.C. Remon. Nail & tag NE side PP	S45°E	95.51
O.C. Remon. Nail & tag W side Fence Cor. Post	N40°E	45.27
± 3' North of Taylor St. CL ± 5' West of 88th CL		



Signed by

*Randal D. Feenstra*

Date

May 9, 1994

Surveyor's Michigan License No. 37275

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983