

# SURVEY & REMONUMENTATION

FEB 27 1998

## SECTION

### Ottawa County Remonumentation LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Ottawa</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>9N</u> R <u>13W</u>	H, G-6
	T <u>9N</u> R <u>13W</u>	E. 1/4 COR. SEC. 16
	T <u>9N</u> R <u>13W</u>	REFERENCE MONUMENT
	T <u>9N</u> R <u>13W</u>	CHESTER TWP.
2. Property Controlling in Section	S <u>15</u> T <u>9N</u> R <u>13W</u>	SEQUENTIAL
	S <u>15</u> T <u>9N</u> R <u>13W</u>	CORNER #3
3. Miscellaneous Property in Sec.	S <u>15</u> T <u>9N</u> R <u>13W</u>	

RECORDED

97 DEC -8 AM 11:39

*Gary K. Kellon*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Maurice J. Rosema Nov. 28 97  
I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G-6

This corner was not set by GLO since it falls in lake, they traversed the section line between G-5 and G-7 (see map on reverse side for method of determining G-6)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-6

Set 5/8" X 2" steel rod with OC remon. cap and mon. box on approx. centerline of E-W bit. conc. road on line between G-6 and I-6  
G-6 - W 551.44'  
I-6 - E 5849.55'

See sketch on reverse side.

I hereby accept this corner as a correct and accurate position of the section corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-6

5/8" x 2" steel rod with OC remon. cap in mon. box on line between G-6 and I-6, 551.44' E of G-6  
SE cor. (siding) of house no. 2611 - N50°W 83.67'  
Set nail and remon. tag in W side P pole - N50°W 26.66'  
SE cor. (foundation) of house no. 2191 - N36°E 94.43'  
SE cor. of brick on SE cor. of garage no. 2221 - N84°W 97.02'  
SW cor. (siding) of house no. 2211 - N65°W 98.75'  
Approx. N-S prop. line between hse. no. 2211 and hse. no. 2191 - E 3'

P.A. 345 OTTAWA COUNTY  
PEER APPROVED 12-1-97

*YDN*



\$ 11.00 CORNER  
2.00 PHOTO

Signed by Maurice J. Rosema  
Surveyor's Michigan License No. 27459

Date Dec. 1, 1997

