LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 19	ATE
For corners in	
ONTONAGON Located In: Corner Code #	REMOLITY TO ACTO
1. Public Land Survey  T48N R 41W T48N R 42W M-7	OCT 3 0 1997
TR  2. Property Controlling S TR	COMMISSION
in Section S T R  3. Miscellaneous S T R  Property in Sec. S T R	
1	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKL
Section Corner common to Sections 18 & 19, T48N R41W & Sections 13 & 24, T48N R42W.	2 -6 - 5 - 4 - 3 - 2 - 1
f. Earl W. Applekamp, in a field survey on August 18 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey is a first of the current manual of survey.	4 - 7 - 8 - 9 - 10 - 11 - 12-5
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, manufacted	6 18 17 16 15 14 13
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	819 20 21 22 23 24 9
on this certificate.	10 30 29 27 26 25
	12 31 32 33 34 35 36
<ul> <li>Description of original monument and accessories and/or subsequent restoration:</li> </ul>	
Original corner established by William A. Burt, U.S. Deputy Surveyor, August 12, 1847. Set Cedar Post.	-
ORIGINAL BEARING TREES:	
8" Aspen S15°E 3.96 feet 6" White Birch N77°W 9.90 feet	
3. Description of corner evidence found and/or method applied in restoring or reestablishing corn	er:
No original evidence was found. Apparent corner location is or road running North & South. This road has been in existence at the apparent corner position a well maintained fence runs a woods & field line. Field is being actively farmed. Corner which lished at intersection of the fence line and centerline of the Corner position is in conformance with the original survey call	since the 1920's. East along a was re-estab- e grayel road.
Research on file with the Ontonagon County Remonumentation Program Representative.	Sail W Good farm
	COUNTY BEPRESENTATION 0-17-97
Description of monument for corner and accessories established to perpetuate locating the position I set a 5/8"X12" rebar with a 3" stampe	
5" below top of gravel road surface. I established a reference monument, a 2½"X30" aluminum pipe with a 3" cap stamped to rea County Remonumentation, T48N R41W, R42W, R.M., S18, S19, S13, 1997, P.S. 17610. I also established 3 other reference object	EARL W.  S24,  PROFESSIONAL  SURVEYOR  SURVEYOR  APPLEAMP  SURVEYOR  SURVEYOR  APPLEAMP  SURVEYOR  APPLEAMP  SURVEYOR  APPLEAMP  SURVEYOR  APPLEAMP  APPLEAM
REF. MON. N75°-21"39"E 34.91' - 9" Aspen N33°-33'-53" Power Pole S38°-54'-18"W 61.67' - 4" Maple N59°-51'-21"	S SURVEYOR O NO. 17610 1
<u> </u>	ember 5, 1997
dirveyor's Michigan License No. 17610	