

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON (County)	Located In:	Corner Code #
1. Public Land Survey	T 49NR 42W	G-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

SURVEY &  
REMONUMENTATION

MAR 23 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Section Corner common to Sections 15, 16, 21 & 22, T49N R42W.

I, Earl W. Applekamp, in a field survey on May 25, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William A. Burt, U.S. Deputy Surveyor, June 10, 1848. Set Sugar Post. ORIGINAL BEARING TREES: 12" Sugar, S40°E, 28 Links, 18" Lynn, N11°W, 23 Links. Corner was restored by Richard L. Drahn, RLS 21564 on July 20, 1980 using retracement measurement to natural feature ties and recovered line trees. He monumented the corner with a 30" long 2" ID cast aluminum monument with a 3 1/4" cast aluminum cap stamped T49N R42W, S15, S16, S21, S22, RLS 21564. The monument was set 1 foot below top of Old M-64. He set two reference monuments. Corner was recorded in Liber, Page 237.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the two reference monuments called for in the recorded certificate. The actual corner monument had been destroyed by the county when replacing a culvert in the road. I re-established the corner using the two reference monuments. One reference monument is a 4" brass capped iron pipe West 35.04 feet. The other is a 16" long plastic reference hub, East 49.04 feet. They remain as future witness to the corner.

DEED GROUP APPROVED  
Earl W. Applekamp  
COUNTY REPRESENTATIVE  
6-9-99

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x12" rebar with a 3" stamped aluminum cap 7" below top of Old Highway M-64. The cap is stamped: County Remonumentation, T49N R42W, S15, S16, S21 & S22, 1999, P.S. 17610. I established two new bearing trees.

Nail in 7" Maple	S60°W	43.00 feet
Nail in 9" Maple	S26°E	77.40 feet

Signed by Earl W. Applekamp  
Surveyor's Michigan License No. 17610

Date June 8, 1999

