

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon Located In: Corner Code #  
(County)  
1. Public Land Survey T 50NR 38W J-5  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

REMONUMENTATION

OCT 30 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, Joseph C. Domitrovich, in a field survey on August 6, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

(J-5) 1/4 Common to Sections 11 & 14, T50N, R38W

A. Description of original monument and accessories and/or subsequent restoration:

1847 - Sylvester Higgins, D.S., set 1/4 post.  
12" Sugar N 57° W 23 links  
12" Hemlock S 72° E 22 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original evidence has been destroyed by farming and road construction. At the corner position, I found an East-West gravel road and an old fenceline to the North. At the intersection of the extension of the fenceline and the centerline of the road, I dug down 18" to the original roadbed and found a 3/4" iron pipe and remains of a rotten wooden post. This pipe falls 18.5 feet West of the theoretical prorated position, but holding this pipe as the corner, the 1/16 fences and old blazed 1/16 lines fall within 1.5 feet of the theoretical position.

I accepted the pipe and rotten wooden post as the 1/4 corner.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 48" rebar driven into the pipe, capped with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; 1/4; S. 11, S. 14; 1997; T. 50N, R. 38W; P.S. 37273. I also established a reference monument (R.M.) to the North, a 2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to indicate that the 1/4 corner is South 27.59 FT.

|                 |                 |          |
|-----------------|-----------------|----------|
| 8" Soft Maple   | N 55° E         | 63.31'   |
| 6" Ash          | S 78° W         | 111.82'  |
| 7" Spruce       | N 64° W         | 65.10'   |
| R.M.            | N 00° 00' 42" E | 27.59'   |
| SE Cor. Sec. 11 | N 89° 22' 54" E | 2687.89' |
| SW Cor. Sec. 11 | N 89° 51' 56" W | 2651.10' |

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by J. C. Domitrovich

Date 8/13/97

Surveyor's Michigan License No. 37273

BEER GROUP APPROVED  
Earl W. Applikamp  
COUNTY REPRESENTATIVE 8-13-97

