

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 50NR 38W

K-1

2. Property Controlling  
in Section

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

SURVEY &  
REMONUMENTATION

APR 07 1998

SECTION

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Joseph C. Domitrovich, in a field survey on November 5, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

(K-1) Closing Corner Common to Sections 1 & 2, T50N, R38W

A. Description of original monument and accessories and/or subsequent restoration:

1847 - Sylvester W. Higgins intersected North boundary 13.60 chains (897.6 feet) west of 1/4 post in Section 33, T51N, R37W, and set post for the Closing Corner.  
10" Sugar S 50° W 24 links  
12" Hemlock S 30° E 35 links  
A stream crossing to the South 13.38 chains (883.08 feet) was noted: "Stream 2 N.E."

1970 - R.S. Scott Engineering for Simar Wasas Road reconstruction plans noted the intersection of an East-West fence and Simar Wasas Road to the South as the approximate Closing Corner. Nothing was set.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner and accessories were not recovered. The East-West fence noted by R.S. Scott Engineering has been obliterated in the area near the corner. I created a position for the Closing Corner at the intersection of centerline of Simar Wasas Road to the South and on the correction line between Standard Corners on the correction line. This position is S 89° 50' 06" W 1089.13' from the South 1/4 Corner of Section 33, T51N, R37W (191.53' longer than noted by Higgins). The stream call to the South works well with this position (875' meas., 883.08' GLO). The stream runs approximately N 50° E, so moving the corner East would cause this distance to be substantially shorter. Longtime residents in the area state that Simar Wasas road has defined the Section line for as long as they remember. I believe this position best represents the original corner position and have monumented it as such.

PEER GROUP APPROVED

Paul W. Applekamp  
COUNTY REMONUMENTATION 11-11-97

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" iron set below the surface of asphalt in centerline of Simar Wasas Rd. with a 3" diameter aluminum cap stamped: COUNTY REMONUMENTATION; T.50N, R.38W; C.C.; S.2, S.1; 1997; P.S. 37273. I also established a reference monument (R.M.) to the West, a 2" x 30" aluminum pipe with a 3" dia. al. cap stamped to indicate that the Closing Corner is East 33.65 feet.

10" Elm	N 89° E	110.02'
Anchor Pole	S 49° E	39.60'
Power Pole	S 51° W	49.24'
R.M.	S 89° 18' 27" W	33.65'
E 1/4 Cor. Section 2	S 02° 12' 12" E	1942.43' (1940.4' GLO)
SW Cor. Section 33 (T 51N, R 37W)	S 89° 50' 06" W	1553.16'

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by J. C. Domitrovich

Surveyor's Michigan License No. 37273

Date 11/10/97

