

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>51</u> N. S., R. <u>37</u> E. W.	<u>A11, C11, B11, C10</u>
2. PROPERTY CONTROLLING IN SECTION_____	, T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	, T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19 , established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner A11: Original monument and accessories not found. Found 1" I.D. iron pipe 1 ft. above ground.

Corner C11: Original monument and accessories not found. Found 1" I.D. iron pipe 1 ft. above ground.

Corner B11: Original monument and accessories not found. Found 1/2" I.D. x 18" iron pipe flush with ground.

Corner C10: Original monument and accessories not found. Found 1" I.D. iron pipe 1 1/2 ft. above ground.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner A11: Re-established 5-12-76 at pipe. This corner was witnessed by M.S.H.D. and has been used as corner for many years.

Corner C11: Re-established 5-17-76 at pipe. This pipe was set from original bearing tree found by William Waara July 1, 1939.

Corner B11: Re-established 5-17-76 at pipe. This pipe was witnessed by M.S.H.D. and used as corner for many years.

Corner C10: Re-established 5-24-76 at pipe. This pipe was set from original bearing tree seen by William Waara June 1, 1939. This pipe was witnessed by M.S.H.D.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner A11: 1" I.D. iron pipe 1 ft. above ground.

Ironwood S 40°W 13.6 ft. S36, NBT
Ironwood S66°E 27.2 ft. S31, NBT
Sugar N51°E 35.8 ft. S30, NBT

Corner C11: 1" I.D. iron pipe 1 ft. above ground.

7" Sugar N30°W 18.0 ft. S30, NBT
7" Sugar N64°E 20.9 ft. S29, NBT
7" Sugar S34°E 33.5 ft. S32, NBT

Corner B11: Set 1" I.D. x 36" iron pipe with 4" aluminum cap.

20" Maple S19°E 10.7 ft. QS, NBT
10" Ash S87°W 19.6 ft. QS, NBT

Corner C10: 1" I.D. iron pipe 1 1/2 ft. above ground.

7" Sugar N60°E 25.5 ft. QS, NBT
8" Sugar N63°W 17.8 ft. QS, NBT

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett
MICHIGAN REGISTERED LAND SURVEYOR
Keith L. Sackett

DATE June 28, 1976

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

