## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in			
Ontonagon (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 51N R 37W	<u>E11</u>	
2. Property Controlling in Section	S T R R S 33 T 51N R 37W S T R	3	
3. Miscellaneous Property in Sec.	S T R S		
4. Lot No. , Rec 5. Private Claims	corded PlatE11 04/1:	0/0040	Register of Deeds Stamp & File Number
above were in conformance with reinstructions of the United States Da Court of Law and /or that the court of the rules of the Michigan Board re-established, monumented, recover	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as required department of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of	d in the current manual of survey and Management or by a decree of 5 above were in conformance with of a Court of Law; established,	6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
on this certificate.			2 31 32 33 34 35 36
(E11) Corner common to post. Hemlock 20 N70E drawing ca. 1907-1910.	= 14 links, Sugar 16 S67W	846 - Established by 9 22 links. Corner shown is not noted but bear	S.W.Higgins Deputy Surveyor. Set wn on old mining company survey rings and distances are given to

- PS, Laurium, MI. 1976 Recorded by K.L.Sackett RLS. Reestablished 5-19-76 at 2" O.D. iron pipe. This pipe fits with stream north and 1/4 corner west. Has been used as corner for many years. NBTs: 7" Birch S50E 7.6', 5" Sugar N27W 14.3', 4" Sugar S31W 13.3'.
- (3-Sec. 33) North 1/16 corner between Sections 32 and 33. Not established in the original survey. Found no record that this corner was established in ca. 1907-1910 mining company survey of Sections 31, 32, and 33. Found no record of subsequent monumentation.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (E11) Found an iron pipe of approximate record diameter, top mushroomed, estimated to be 1.5" O.D., set firm, at record bearing and distance from two remaining 1976 witnesses: the Y.Birch SE and Sugar NW, both in good condition with overgrown blazes. The position of the pipe is in substantial accord with the bearings and distances given on the mining company survey drawing, and I accept the pipe as the best available evidence of the position of the original corner.
- (3-Sec. 33) Established the corner midway and on the Section line between Section corner 1345.32' northerly and Quarter corner 1345.32' southerly. The true bearing of this line was observed to be SO4 deg. 12'50"W. A corner to an old unmaintained barbed wire fence running east and south from the fence corner, approx. 90% down on the ground is S86W (true bearing) 143' distant. The fence line passes 10' south of the corner monument. From the fence corner, the fence runs straight to the Quarter corner E12 and its direction closely approximates the Section line E13 to E12, produced northerly.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(Ell) Found 1.5" O.D. iron pipe.	
Set measuring nail with MDNR tag	in the side of:
11" Y.Birch S48E 7.8' old blazes	(1976 NBT)
7" Sugar N22W 14.8' do	do
12" Sugar \$08W 15.5' mrkd "\$32	NBT"
	NBT"
Set cedar post adjacent. Bearing	s are magnetic.

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. The mon. leans a little west. Top-center of the cap marks the corner position. Set measuring nail with MDNR tag in the side of:

mrkd \*1/16S BT\* 4" Sugar N38E 18.45' 4" Sugar S70E 9.6' do 10" Sugar S20W 18.9'

do 10" twin Sugar N70W 1.1' Cedar post adjacent. Bearings magnetic.

FORM APPROVED BY MICHIGAN STATE BOA

Signed by Stephen	Sys	lost.	Date	09/07/2010	1	
Surveyor's Michigan License No.		33986			1	ì

For the Michigan Department of Natural Resources and Environment, Forest Management I visionLAND

SURVEYOR

STEPHAN SZYSZKOSKI

16399