

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 37W L7
T R
T R
T R

2. Property Controlling
in Section

S 24 T 51N R 37W 8

3. Miscellaneous
Property in Sec.

S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

L7 Sep 22 2004

8 Sep 21 2004

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(L7) Quarter corner common to Sections 13-24. Reestablished midway and on line between Section corners by K.L.Sackett RLS in 1976. Set 1"IDx36" iron pipe with 4" aluminum cap. 7" Maple N51W 13.7', 8" Sugar S70W 17.1', 12" Sugar S65E 21.5', Squared 4" Sugar North 2.1'.

(8-Sec. 24) West 1/16 corner, Section 24. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L7) Recovered the 1976 monument in good condition, and at record bearing and distance from the Sugar SE, now a stump, and the squared Sugar North 2.1'. The remaining 1976 NBTs have been disturbed. The monument is 1.36' east of the record midway position and I accept same as a careful and faithful reestablishment of the position of the original corner.

(8-Sec. 24) Established the corner midway and on a straight line between Quarter corner 1284.57' west and Center of Section 1284.57' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L7) Found 1"ID iron pipe with 4" alum. MDNR cap. Set measuring nails with tags in:

24" Hemlock North 42.1' mrkd "1/4S NBT"
9" Sugar S77E 34.7' do
9" Hemlock S07E 49.6' do
6" Sugar N79W 31.2' do

Set sq'd cedar post adjacent. Bearings are magnetic. Distances are to nail with tag.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nails with tags in:

9" Sugar S61E 14.8' mrkd "1/16S BT"
14" Sugar S06E 29.0' do
12" Sugar S76W 41.6' do
9" Spruce N38W 43.7' do

Set sq'd cedar post adjacent. Bearings are magnetic. Distances are to nail with tag.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/3/04

For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995