

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 37W L8  
T 51N R 37W K9  
T R  
T R  
T R  
T R  
T R  
T R

2. Property Controlling  
in Section

S T R  
S T R  
S T R  
S T R

3. Miscellaneous  
Property in Sec.

4. Lot No. , Recorded Plat  
5. Private Claims

Register of Deeds Stamp & File Number

Sep 22 2004

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(L8) Center of Section 24. Not established in the original survey.

(K9) Corner common to Sections 23-24-25-26. 1976: K.L.Sacket RLS found and accepted a 1-3/4" ID iron pipe, projecting 3' above ground. 1976 witnesses: 9" Sugar N81E 19.7', 14" Sugar N04W 24.9', 8" Y.Birch S51E 20.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L8) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.

(K9) Recovered and accepted a 1-1/4" ID iron pipe projecting 3' above ground at record bearing and distance from the 1976 witnesses, now all dead. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L8) Set 1"IDx32" I.pipe with 4" alum. MONR cap. Set measuring nails with tags in:

9" dbl Maple N23E 16.7' mrkd "C1/4 BT"

17" Sugar S37E 20.7' do

8" Sugar in clump S86W 20.8' do

10" Maple N54W 10.7' do

Set sq'd cedar post adjacent. Bearings are magnetic. Distances are to nail with tag.

(K9) Found 1-1/4" ID iron pipe. Set measuring nails with tags in:

26" Y.Birch S74E 31.1'\* mrkd "S25 NBT"

11" Hemlock S44E 22.6' do

10" Hemlock S62W 24.0' "S26 NBT"

14" Maple N27W 8.5' "S23 NBT"

Set sq'd cedar post adjacent. Bearings are magnetic. Distances are to nail with tag. \* = This NBT has old face with axe marks. Approx 7" of overgrowth.

Signed by Stephan J. Szyszkoski

Surveyor's Michigan License No. 33986

Date 11/3/04



For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1985