

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Ontonagon</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>13</u> T <u>51N</u> R <u>37W</u>	<u>10</u>
	S <u>12</u> T <u>51N</u> R <u>37W</u>	<u>C-N-SW 1/64</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 10 06/03/2009 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 13) South 1/16 corner between Sections 13 and 14. Not established in the original survey.

(C-N-SW 1/64 Sec. 12) 1/64 corner being the SE corner of the N1/2 of the NW1/4 of the SW1/4 of
Section 12. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 13) Established the corner midway and on the Section line between Quarter corner 1357.62'
north and Section corner 1357.62' south.

(C-N-SW 1/64 Sec. 12) Established the corner midway and on a straight line between 1/16 corner #8
666.73' north and 1/16 corner #11 666.73' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Maple N46E 10.95' mrkd "1/16S BT"
7" Hemlock S19W 8.6' do
14" Cedar S82W 25.6' do
15" Maple N47W 21.3' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(1/64) Set 1"IDx32" I.pipe w/ 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Maple N89E 14.55' mrkd "1/64S BT"
6" Hemlock S04E 21.9' do
6" Maple S75W 20.9' do
11" Y.Birch N32W 16.5' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/16/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

