

4.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Ontonagon

(County)

Located in:

Corner Code #

1. Public Land Survey

T 51N R 38W J12
T 51N R 38W J13

**2. Property Controlling
in Section**

S T R
S T R

**3. Miscellaneous
Property in Sec.**

S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Oct 07 1996

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34						
13													

A. Description of original monument and accessories and/or subsequent restoration:

(J12) Center of Section 35. Corner not established in the original survey. Corner was recorded in 1971 by A.O. Enger, RLS as follows: "Found a cross (+) chiselled on a rock, pointed out to Survey Party Chief K. Sackett by a long time local resident, Mr. Nick Lukkarilla, as being the center of the section. Measurements along E & W 1/4 line and East section line tend to support the location. Corner accepted as found. Set a 1" I.D. x36" iron pipe with 4" aluminum cap 1.3 ft. south of cross for a witness corner. Witnesses to iron pipe: Red Oak 7 N64.5E 40.2', Elm 8 N83E 71.7". Found no subsequent record.
(J13) Quarter corner on the South Side of Section 35. Established in 1847 by Austin Burt: Ironwood post for quarter section corner. 12" Cedar N36E 50, 10" Y. Birch N10W 12. Corner is shown on the Plat of Mass City as "1/4 post stone" and a distance to the SE corner of Section 35 can be derived as 2641.5 ft. Map #132 in the Plat Cabinet at Ontonagon Co. Register of Deeds, an undated, unsigned blueprint, shows that a "stone" marks the 1/4 corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J12) Found the chiselled cross and pipe, at record bearing and distance from the remaining Red Oak 8T. the Elm was not recovered. The pipe's cap is now gone and the top of the pipe is somewhat broken. It has apparently been sheared off. The cross is plainly visible. Corner recovered and re-witnessed by B.Wheeler, Baraga District Office.
(J13) Recovered a pyramid shaped stone, approx. 1' high, with a base of 1.5'x0.5'. Found four recent witnesses made to this stone, made by Gerald Carlson, a surveyor in Marquette County. Also recovered a 3/4" rebar adjacent to a 3' tall 1/2" iron pipe nearby, apparently left as a witness by someone. Measured the distance east to Section Corner and found it to be 2642.28 ft. This stone has been apparently been used as the corner by local surveyors. Accepted the stone as the best available evidence of the position of the original corner. The witnesses shown below are those recovered. Corner recovered and witnessed by B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J12) Found + cut in rock
15" R. Oak N60E 39.9'
26" Sugar S10E 6.6'
15" R. Oak S82W 46.3'
15" R. Oak N69W 62.2'
1" iron pipe, sheared off, South 1.6'
Bearings are magnetic.
Placed 4" squared ironwood post adjacent to the pipe.
(J13) Found pointed stone. Recovered the following new bearings trees found with nails set in side blazes:
18" Sugar N77E 10.2'
7" Sugar S20E 41.0'
6" Sugar N83W 6.5'
7" Sugar N25W 18.7'
3/4" rebar & 3' tall IP N43E 2.2'
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date Sept. 17, 1997

For the Michigan Department of Natural Resources - Forest Management Division