

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Ontonagon
(County)

Located In:

Corner Code #

1. Public Land Survey T 52N R 40W (G-12/13) #3
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____

**SURVEY &
REMONUMENTATION**

MAY 22 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Joseph C. Domitrovich, in a field survey on October 1, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G-12/13) Meander Corner Common to Sections 33 & 34, T52N, R40W

1845 - William A. Burt set post

10" W. Pine S 72° E 34 links

1928 - E.J. Donnelly, C.E., For Supervisor Carroll's Plat of Government Lots 3 & 4, Section 34, shows a concrete monument at the SW Corner of Section 34 (which he shows as common with the sections in the township to the South) and he also shows a concrete monument 1/4 mile North of the Section corner, "1/8" corner.

1969 - M.S.H.D. for M-64 Highway plans, show they found monuments as per Donnelly.

1979 - Robert Mick, P.S., in Ontonagon County Airport Survey on file with plats at Ontonagon County Register of Deeds, shows that Donnelly mistakenly used the closing corner to set up his section line for his plat and that the true Section line falls 43.56' West of the plat line.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a star drill in concrete at the Southwest Corner of Carroll's plat and a 3/4" iron in concrete at the "1/8" Corner as per Donnelly and M.S.H.D. After extensive retracement along the township line and in sections to the South, I came to the same conclusion as Bob Mick, that Donnelly and the M.S.H.D. mistakenly called the Closing Corner of Sections 4 & 3, T51N, R40W, a common Corner and used it to set up the Section line in Sections 33 & 34, T52N, R40W. Original notes indicate that the Closing Corner fell 43.56' East of the Standard Corner. I therefore set up the Section line 43.56' West of the Plat line and parallel to it and established a Witness Corner to the Meander corner on the re-established Section line at high-water mark.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: W.C.M.C.; S. 33, S. 34; T.52N, R.40W; 1996; P.S. 37273; COUNTY REMONUMENTATION. Corner falls 36' South of shore of Lake Superior.

Witnesses:

1/2" Iron, #17610 S 85° E 43.69' (On Plat Line)
10" Twin W. Birch S 65° E 8.05'
12" W. Birch S 28° E 19.73'
15" W. Birch South 23.86'
Steel Sign Post North 1.27'

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE
10-16-96



NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by J. C. Domitrovich
37273

Date 10/15/96

Surveyor's Michigan License No. _____

- SKETCH ON BACK -
217

T52N R40W

