LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| | | 0 | 1 | | | |
|---|--|---|---|----------------------|--|----------------------------|
| Ontonagon (County) | _ Located In: | Corner Code # | | 83 | | 3 |
| 1. Public Land Survey , | TR | 37W G9 | | | | |
| 2. Property Controlling in Section | S T R S 10 T 53N R S T R | 37W 16 | | | | |
| 3. Miscellaneous Property in Sec. | S T R S T R S T R | | _ | | | |
| 4. Lot No. 5. Private Claims | corded Plat | 07/06/0040 | | Register of Dee | | E Number |
| I, Stephan J. Szyszkoski, in that under requirements of P.A. above were in conformance with instructions of the United States a Court of Law and for that the other ules of the Michigan Boar re-established, monumented, recov | 74, Michigan P.A. of 1970, the regulations and rules therefore Department of the Interior, But corner points mentioned in lines of of Land Surveyors or by a | e corner points mentioned in linguistry as required in the current manureau of Land Management or by a 3, 4 and 5 above were in confo | ual of survey 5 a decree of 6 promance with 7 | -18 -17 - -19 -20 | 9 10 10 15 15 15 15 15 15 15 15 15 15 15 15 15 | 11 12 |
| 3 | ners, all in the same town ar | | 9 10 11 12 | | 28 27 | -26 -2 5 -35 -36 |

ption of original monument and accessories and/or subsequent restoration:

(G9) Corner common to Sections 21-22-27-28. 2006 - Corner remonumented and approved by Ontonagon County Peer Group. Todd G. Maki PS #49300 set a stamped alum. Berntsen monument as described in LC7 The monument perpetuates the 1979 position recovered and recorded by K.L.Sackett RLS #19006. The 1979 accessories are 5" Sugar S38E 13.0', 7" Y.Birch S15W 11.4', 16" Sugar N85W 22.4'. The 2006 accessories are 14" Sugar S36W 18.89', 9" Sugar N40W 11.64', 11" Sugar N57E 32.54', Steel rail w/survey marker sign S56E 1.3'.

(16-Sec. 10) East 1/16 corner between Sections 10 and 15. 1967 - Established by F.J.Bray RLS #13575 midway and on line between Section and Quarter corners. Set 1 1/4" x 30" iron pipe, buried. 10" Hemlock N16E 34 links, 8" Hemlock S16E 55.5 links, 13" Hemlock S56W 82 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G9) Found the 2006 monument as described and in good condition. Found the 1979 witnesses at record bearing and distance: the Sugar S38E is in good condition. The Y.Birch S15W and Sugar N85W are dead and down. The 2006 witnesses made by Mr. Maki are not present and an inspection of the record of corner E9 reveals that his witnesses for G9 LC7 - PG349 are the witnesses that exist at corner E9, recorded in LC7 - PG358. I accept the monument as a careful and faithful perpetuation of the position of the original corner.

(16-Sec. 10) The 1967 monument was recovered bent over by road grader. The lower portion of the monument is plumb and at record bearing and distance from the remaining two Hemlock BTs SE and SW. Removed the 1967 pipe and drove a new monument at the position of record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G9) Fd. 3" dia. alum. Berntsen monument & cap Found duplex nail in bottle cap in the side of: 6" Sugar S38E 13.2' old blazes 11" twin Maple S87E 8.05' do 6" Sugar N13W 14.5' Sign post with survey marker N71W 1.5' Set measuring nail with MDNR tag in: 15" Maple \$54W 27.55' mrkd "S28 NBT" Bearings are magnetic.

(16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Hemlock S11E 37.05' old blazes 1967 BT 14" twin Hemlock S61W 54.55' do do 7" Hemlock N69W 53.9' mrkd "1/16S BT" 9" Hemlock N23E 25.75' do Bearings are magnetic.

Signed by Date 11/29/2012 Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J SZYSZKOSKI LAND **URVEYOR** No. 33986 60 CAND SUP S. JAN, 28, 1971

FORM APPROVED BY MICHIGAN STATE BOARD OF PRO

Revised May 14, 1975 Revised Jan., 1983

16952