

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T 53N R 37W	D7
	T R	
	T R	
2. Property Controlling in Section	S T	
	S 17 T 53N R 37W	D6
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on D7 08/01/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D7) Quarter corner common to Sections 17 and 20. 1979 - K.L.Sackett RLS found and accepted a 3/4"
ID iron pipe set by M.C. Larsen in 1955 from an original B.T. 1979 witnesses: 22" Sugar N58E 6.9',
12" Sugar S10W 2.8', 5" Sugar N11W 13.3'.

(D6) Center of Section 17. 1980 - Established by K.L.Sackett RLS at the intersection of 1/4 lines.
Set 1"IDx36" I.pipe with 4" alum. MDNR cap. 22" W.Pine S37E 8.8', 4" Maple S82W 5.6', 4" Maple N28E
15.7'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D7) Found the 3/4" ID iron pipe of record, projecting 15" above ground, at record bearing and
distance from two remaining witnesses from 1979: 18" Sugar N61E with scribing plain, 7" Sugar N06W
with overgrown blazes. Accepted same as a careful and faithful perpetuation of the position of the
original corner.

(D6) Found the 1980 monument in good condition, substantially at the record position, and at record
bearing and distance from two remaining BTs: a 30" W.Pine S32E with overgrown blazes, and a 4" Maple
S85W with scribing plain, both in good condition. Accepted the monument as a careful and faithful
establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D7) Fd. 3/4" ID iron pipe.
Set measuring nail with MDNR tag in the side of:
18" Sugar N61E 7.45' old scribing 1979 NBT
7" Sugar N06W 13.35' old blazes do
10" Sugar S68W 29.75' mrkd "1/4S NBT"
11" Y.Birch S64E 9.25' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(D6) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
30" W.Pine S32E 9.9' old blazes 1980 BT
4" Maple S85W 5.85' scribing do
9" Maple N03W 6.1' mrkd "C1/4 BT"
5" Spruce N75E 24.7' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/29/2012

For the Michigan Department of Natural Resources, Forest Resources Division

