

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Presque Isle

(County)

Located In

Corner Code #

1. Public Land Survey

T 33N R 2E I-11
T 33N R 2E I-12

2. Property
Controlling in
Section

S T R
S

3. Miscellaneous
Property in Section

S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

Register of Deeds Stamp & File Number

I, Carl T. Kiiskila, in a field survey on June 18, 2007 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-11 G.L.O. G.H. Cannon, 1851, Set quarter section post

Wit: Spruce Pine 12" S20°W 44 links

Spruce Pine 12" N14°E 33 links

I-12 G.L.O. G.H. Cannon, 1851, Set quarter section post

Wit: Spruce Pine 4" S77°E 25 links

Spruce Pine 6" N85°W 24 links

Michigan Department of Conservation surveyor Marcus Schaaf R.L.S. #3104 sunk iron for corner while surveying in the area circa 1940. No witnesses or type of monument given.

Michigan Department of Conservation surveyor Marcus Schaaf R.L.S. #3104 sunk iron for corner while surveying in the area circa 1940. No witnesses or type of monument given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

I-11 Re-established the section corner to sections 26,27,34 & 35 by doubling down Marcus Schaaf East quarter of section 27 and the South 1/16 on the East line of section 27.

I-12 Found a 2" pipe in the intersection of North -South and East -West fire lanes.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-11 Set a 5/8" re-rod with P.S. Cap #33981

Wit: Nail & Tag in SE/side 8" J. Pine N42°E 39.98'
Nail & Tag in S/side 6" J. Pine N86°E 28.65'
Nail & Tag in N/side 3" Oak N63°W 25.37'
Nail & Tag in W/side 3" Oak S36°W 55.43'
Ctr North - South road East 2.5'

I-12 Added P.S. Cap #33981 to the found 2" pipe

Wit: Nail & Tag in N/side 12" R. Pine N45°W 55.02'
Nail & Tag in E/side 13" R. Pine N13°W 51.14'
Nail & Tag in N/side 13" R. Pine N74°E 47.10'
Nail & Tag in SE/side 16" Oak S33°W 68.04'
The pipe falls in the Center of the road intersection

Signed by:

Carl T. Kiiskila

Date:

8-20-07

Surveyor's Michigan License No.:

33981

