LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

	•		
For Corners In: Roscommon (County)	Located In	Corner Code #	
1. Public Land Survey	T 24N R 04W	D-5	
Property Controlling in Section	s		
Miscellaneous Property in Section	s	·	Register of Deeds Stamp & File Number
, ,	S T R		A B C D E F G H I J K L M
			¹
4. Lot No:	Recorded Plat:		2 - 6 5 4 3 2 1
			3
5. Private Claims:			
_			4 - 1 - 1 - 1 - 1 - 1 - 1 - 1
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>December 28, 2011</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in			5 6 -18 17 16 15 14 13 7
the current manual of survey instructions of the United States Department of the			
interior, bureau or Land Management or by a decree or a Court or Law and/or that the			8 -19 -20 -21 23 23 24
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules			9
of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			10 - 30 - 29 - 26 - 27 - 26 - 25
established, re-established	, monumented, recovered, round as ex	pressed below.	11
NOTE: Not more than	2 corners, all in the same town a		
be recorded on this certificate.			12 -31 -32 -33 -34 -35 -36
13			13

- A. Description of original monument and accessories and/or subsequent restoration:
- D-5 South 1/4 corner section 8, T24N,R4W

GLO 1852 Addison P. Brewer set quarter section post Wit. 10" S. Pine N28°W 27 lks 9" W. Pine S66°E 6 lks

2001 Roscommon Co. Remonumentation Liber 3, Page 726 Marvin Myers PS#31600 set a standard County monument By single proportion measurement

Witnesses:

Spike in SW side 14" Norway S52°E 34.78' Spike in E side 14" Norway S18°W 75.38' Nail & tag in ORV trail stop sign post N54°W 53.28' Nail & tag in East side 6" Oak N18°W 35.05' Set Carsonite Post N65°E 46'±

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- D-5 South 1/4 corner section 8, T24N,R4W The standard County monument was removed by pipeline construction reestablished the South 1/4 corner section 8, by single proportion measurement.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5 South 1/4 corner section 8, T24N,R4W

Set 1"x36" galvanized pipe with standard DNR Cap

Witnesses:

Signed by:

N41°E 73.87' to set N&T on SE side 24" W. Pine S56°E 34.66' to fd nail on SW side 18" R. Pine S14"W 75.34' to fd nail on E side 16" R. Pine N20"W 35.68' to set N&T on E side 10" R. Oak N63°E 45.9' Carsonite Post Centerline of N-S road is 3' East

Surveyor's Michigan License No.:

33981

OF MICHIG CARL IISKIL. LAND SED LAND SURVE

6-28-12

Date: