

APPROVED BY PEER GROUP SAGINAW COUNTY REMONUMENTATION

P.A. 345 OF 1990  
SAGINAW COUNTY

LIBER 1956 PAGE 1119

Like 7 Page 28

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Saginaw

(County)

Located In:

Corner Code #

12 N. 3 E.

C-9

1. Public Land Survey

T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Property in Section

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Ronald C. Prevost

Nov. 29

95

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-9 Post Set by Wampler in 1822

3/4" Pipe set by J.W. Martin (Spicer) in 1947, in line with fence to West & 33' East of Fence Corner at Center North and South Road. This area had been excavated with a wide digging the previous year (1946) by J.W. Martin.

L.C.R.C. L1, P145, 3/4" pipe, 1971, Sides.

L.C.R.C. L1, P178, 3/4" pipe, 1972, McKelvey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Found 3/4" pipe, 1 witness from L1 P145, 2 witnesses from L1 P178 agree. See Section C. Also found 5/8" pipe 2.49' to North, origin unknown.

Dug at both irons, nothing further found, North iron looks fairly new.

Is accepted as the best available evidence of the position

of the original corner. Ratified by Saginaw Co. Peer Group 11-29-95

REMONUMENTATION

FEB 22 1996

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Replaced 3/4" pipe with 5/8" Re-rod, Saginaw Co. Brass Cap, and Monument Box. 11-29-95

East 32.60 Nail & Disc. in Power Pole (32.60 R)

West 61.90 Nail & Disc. #13042 in Power Pole (62.00 R)

N.55°E. 46.40 Nail & Disc. in SE Face 30" Cottonwood (46.47 R)

N.15°W. 202.91 Ctr. Hyd.



Signed by

*Ronald C. Prevost*

Date

12-27-95

Surveyor's Michigan License No. 24612