LIBER 1924 PAGE 774

PPROVED BY PEER GROUP

P.A. 345 OF 1990 SAGINAW COUNTY

SAGINAW COUNTY REMONUMENTATION PROJECT

LAND CORNER RECORDATION CERTIFICATE

SURVEWS

Filing Requirement of Act 74, Mich. P.A. 1970

DEC 14 4 08 PH '94

MILL ATT DOUBLE REGISTER OF DEEDS SACINAN COUNTY MICH

SURVEY&					C A C	WAMI	COU	AJ.A WI
For corne BEMONUMENTATOLATED In:	Corner Code #				SAC) (IV		
APR 2 4 1995 1. Public Land Survey	D-13	Left. Regist		•	Out			
4. Lot No, Recorded Plat 5. Private Claims		1	A B	C D	E F G	; H	J K	LM
I, John H. Rauser , in a field survey on June 30, 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in current manual of survey instructions of the United States Department of the Interior, Bureau of La Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law; established, re-established, monumented, re-monumented, recovered, found expressed below:		3 , 4 ed 5 he 5	7	8	9	10	-11	12
		fa	19	20	21	22	- 23	24
NOTE: Not more than 4 corners, all in the same town a on this certificate.	ind range, may be recorded	d 10 11 12	-		28 33	27 34	26 35	25 36
A. Description of original monument and accessories and	l/or subsequent restoration:	13		•			Lľ	
(D-13) S 1/4 Cor., Sec. 32, T13N-R3E Wood post placed by J. Wampler, Depu N16°E 7 lks (4.62') 10" Ash S13°E 6 lks (3.96') 9" Beech	ity Surveyor, 1822					_		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L. 1448, Pg. 1094, Saginw County Records.

(D-13) Standard S 1/4 Cor., Sec. 32, T13N-R3E
Found no evidence of original government corner. Recorded witnesses as stated in "A" above have been cut down or removed. Stumps of apple trees exist & check with record 0.2' +/-.
Found bent "T" iron 0.1' +/- below asphalt surface inconsistent with record. Removed iron and dug to 3' +/- below surface, found wood, rock, crockery & steel shackle with 3/4" iron bar 1.5' +/- below original asphalt. Fit record distance to pipe at D-1, T12N-R3E and is accepted as a careful and faithful perpetuation of the position of the original corner.

1975 Act 132 by Arthur H. Leach, P.S. #7236, Rec. L. 1452, Pg. 934, Saginaw County Records.

L.C.R.C. by Arthur H. Leach, P.S. #7236, Rec. L. 3, Pg. 112 Saginaw County Records.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (D-13) N 1/4 Cor., Sec. 5, T12N-R3E

 Reset 5/8" rerod w/brass cap stamped Saginaw County Monumentation,

 P.S. #39096 over existing 3/4" iron bar. Placed monument box flush w/ pavement.

 N40°W 32.63' Set 3/4" pipe w/cap #39096 in S ditch bank N side of road 12'± N of N edge pvmt

 N70°E 57.25' S edge traffic sign

 S34°E 135.01' Set spike w/tag #39096 in SW fce PP

 S09°W 60.76' Set spike w/tag #39096 in fce 6" apple tree

 West 44.34' D-1, T12N-R3E

 JOHN H.

 RAUSER

Signed by /ohn H. Kauss

_ Date _

FORM APPROVED BY MICH

BOTTOM AND SURVEY RE, JAN. 23, 197
EVISED MAY 14, 197
REVISED JAN, 198
REVISED JAN, 198
REVISED JAN, 198

Professional Buhveyor

Surveyor's Michigan License No.