	LIBER 1 PAGE 480	
I	REMONUMENTATION & TON LAND CORNER RECORDATION CERTIFICATE	
Fo	REMONUMENTATION BATTON LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970  Sanilac  Public Land Survey R 10 10 10 10 10 10 10 10 10 10 10 10 10	RECEIVED FOR RECORD
_	Sanitac Corner Code #	94 DEC 16 AM 9: 39
1.	Sanilac         ONOR         1095         Located In:         Corner Code #           Public Land SurvAPR 10 10 10 10 10 10 10 10 10 10 10 10 10	LIBER NO PAGE NO. 480
2	T R	REGISTÉR OF DEEDS SANILAC CO., MICHIGAN
	in Section ST R	ciatas of Boods Otamo 6 File Manufact
<b>U</b> .	Property in Sec. S T R	gister of Deeds Stamp & File Number
	Lot No, Recorded Plat	- A B C D E F G H I J K L I
5.	Private Claims	2 6 5 5 4 3 4 2 4 3
.•		3 4 7 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
l, _	John A Milletics , in a field survey on Dec 1 , 19 94 .	5
in cui Ma ab Co exp	hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the crent manual of survey instructions of the United States Department of the Interior, Bureau of Land nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:	6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NC	TE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	12 31 32 33 34 35 36
A.	Description of original monument and accessories and/or subsequent restoration:	,
	I - 11 GLO Notes Set Post: Elm 22 N 82 W 5, Elm 15 N 81 E 32	
	Act 74 Form NONE Act 132 Form Liber 4 Page 276, Liber 2 Page 599 Unrecorded Surveys Dated 7-1-80, Dated 12-10-87	
	MDOT Right of Way Book Page 55 & 16	
	Road Comm NONE Drain Comm NONE	
В.	Description of corner evidence found and/or method applied in restoring or reestablishing	g corner:
	I - 11 NE Cor Section 34 T10N-R14E Found Monu Box	Approved Peer Board Meeting Dec 16, 1994
		. /
	, -	
C.	Description of monument for corner and accessories established to perpetuate locating to	he position of the corner:
•	I - 11 NE Cor Section 34 T10N-R14E Found Monu Box	THINHINININININININININININININININININI
	N45°E 49.90 to a nail in a Power Pole	
	N45°W 49.60 to a nail in a Power Pole S45°W 55.60 to a nail in a Power Pole	John A. Milletics Land Surveyor
	S45°E 58.05 to a nail in a Power Pole Monu Box exist on both centerlines	John A. Milletics A. Land Surveyor No. 25859
	Mond Doy dy Tar on poen center trues	ンペラー・ション

Surveyor's Michigan License No. 25859

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Dec 11, 1994