

JAN 22 2001

LIBER

3 PAGE 37

RECEIVED FOR RECORD

00 NOV 27 AM 8:55

SECTION

2000 Remonumentation Program  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 3 PAGE NO. 37  
MICHELE VANHORN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T 12N R 15E H - 13  
T R  
T R  
T R  
S T R  
S T R  
S T R  
S T R

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. , Recorded Plat  
5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

John A. Millettics, in a field survey on May 1, 19<sup>xx</sup> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Hemlock 15" N36°E 16 1/2 Links  
Beech 9" N33°W 15 Links

Act 132 - Liber 4 Page 299 Sanilac Land Survey  
Recorded Plat Liber 1 Page 8 - Carson's Plat of Carsonville

L.C.R.C. - None

Unrecorded Surveys-Millettics Dec 1989, Millettics Dec. 1998

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 13


S 1/4 Corner Section 34 T12N-R15E

Found 5/8" Iron Bar in Monu. Box

West 2638.59 feet to the SW Corner Section 34

East 2642.49 feet to the SE Corner Section 34

Accepted as best evidence



3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 13

S 1/4 Corner Section 34 T12N-R15E

5/8" Iron Bar in Monu Box

North 33.00 feet to a 1/2" Iron

N25°E 28.40 feet to a nail in a Power Pole

S30°W 24.35 feet to a nail in a Power Pole

West 20.40 feet to a 1/2" Iron in a Monu. Box

South 30.00 feet to a nail in a 24" Maple

West 2638.59 feet to the SW Corner Section 34

East 2642.49 feet to the SE Corner Section 34

APPROVED PEER BOARD  
MEETING NOV 25 2000

igned by

urveyor's Michigan License No. 25859

Date Nov 15, 2000