

JAN 22 2001

LIBER

3 PAGE 59

RECEIVED FOR RECORD

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
2000 REMONUMENTATION PROGRAM

00 NOV 29 AM 11:11
LIBER NO. 3 PAGE NO. 59
MICHELE VANHORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey T12N R 16E H - 13
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

2000

I, John A Millettics, in a field survey on May 1, ~~1999~~ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5				4		3		2		1	
3													
4	7	8				9		10		11		12	
5													
6	18	17				16		15		14		13	
7													
8	19	20				21		22		23		24	
9													
10	30	29				28		27		26		25	
11													
12	31	32				33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Maple 11" N79°W 19 Links

Hemlock N81½°E 12 Links

Act 132 - Liber 3 Page 363 & Liber 4 Page 579

Unrecorded surveys - Millettics July 1993 & Millettics July 1997

L.C.R.C. - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 13

S 1/4 Corner Section 34 T12N-R16E

Found no evidence of corner on site - State Highway Department removed during construction

West 2649.60 feet to the SW Corner Section 34

East 2661.05 feet to the SE Corner Section 34

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 13

S 1/4 Corner Section 34 T12N-R16E

1/2" Iron Bar with cap in concrete

North 5.00 feet to the centerline of M-46

North 65.00 feet to a 1/2" Iron Bar

East 38.60 feet to the N 1/4 Corner Section 3

S40°E 71.70 feet to a nail in a Telephone Pole

S45°E 87.85 feet to a nail in a 8" Poplar

N05°E 64.86 feet to a Michigan Bell Riser Box

West 2649.60 feet to the SW Corner Section 34- East 2661.05 feet to the SE Corner Sec. 34

Signed by John A MilletticsDate Nov 15, 2000Surveyor's Michigan License No. 25859

APPROVED PEER BOARD
MEETING Nov 25, 2000
gn

