SURVEY & REMONUMENTATION

FEB 0 R 2000

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970 PAGE 209 For corners in Mottville Township STATE OF MICHIGAN ST. JOSEPH COUNTY Located In: Corner Code # St. Joseph FILFI (County) G-1 1. Public Land Survey T<u>8S</u> R<u>12W</u> 16 NOV 1999 12:51:40 PK R CYNTHIA L. JARRATT REGISTER OF DEEDS 2. Property Controlling R in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number _ , Recorded Plat 4. Lot No. 5. Private Claims 2 I, <u>David W. Mostrom</u>, in a field survey on <u>May</u>, 19 <u>99</u> do state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations 99 do state that under requirements 5 and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, 6 Bureau of Land Management or by a degree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 7 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, £ established, re-established, monumented, recovered, found as excressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 77 (G-1) NE CORNER SECTION 4, T8 S, R 12 W NOTE: THIS IS A COMMON CORNER WITH (G-13) T 7 S, R 12 W A Description of original monument and accessories and/or subsequent restoration: 1976 LCRC IN BOOK 2, PAGE 64 *3/4" PIPE IN MON. BOX 1966 ROAD COMMISSION *1/2" PIPE THROUGH OLD DELAYED 13" W. OAK = N50 1/2°W 41.58' 9" W. OAK = N14°E 122.76" *P. POLE = N46*E 42.9' WOOD STAKE IN MON. BOX NW HSE COR = \$65°W 89.89' *P. POLE = \$44°E 46.5' 1864 SURVEY IN BOOK A, PAGE 46 24" MAPLE = \$18°W 93.38" NE COR. HSE = \$45°W 67.4' STONE FROM ORIG. BEARING TREES *P. POLE = N60°E 42.87 18" W. OAK = N50°W 41,58' *P. POLE = \$77°E 109.04" 1995 SURVEY BY MOSTROM 9" W. OAK = N14°E 122.76" *FOUND 3/4" PIPE IN MON. BOX *P. POLE = N60°E 42.85° *P. POLE = \$77°E 109.04" *P. POLE = \$45°E 54.5' *26" ELM = \$80"W 152.0" O' OF MICA CAN DAVID W. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 3/4" (OD) X 36" PIPE IN MON. BOX DUG 5' DEEP HOLE BUT FOUND NOTHING UNDER PIPE MOSTROM PROFESSIONAL SURVEYOR CORNER FALLS IN CENTERLINE OF BURKE ROAD & 0.5' NORTH OF CENTERLINE DICKENSON ROAD P. POLE = N60°E 42.84' No. P. POLE = \$77°E 109.00° AROFESSIONAL MINISTRALIA P. POLE = \$45°E 54.5° OFESSIONAL STATEMENT 30" FLM = \$80°W 152.0" SET 5/8" X 48" IRON BAR WITH STD. CAP IN PLACE OF PIPE FOUND IN MON. BOX C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 5/8" X 48" IRON BAR WITH STD. CAP IN MON. BOX N & W 2.0' HIGH IN SE SIDE OF P. POLE = N60'E 42.85' N & W 3.0' HIGH IN N. SIDE OF P. POLE = S77°E 108.67' RATIFIED BY PEER GROUP N & W 3.0' HIGH IN NW SIDE OF P. POLE = N32°E 62.30' IN ACCORDANCE WITH P.A. 345 N & W 1.0' HIGH IN NE SIDE OF P. POLE = \$45°E 54.50' NOV. 8 ON , 1999 N & W 2.0' HIGH IN N. SIDE OF 30" ELM = \$80°W 152.00' _CO. REPRESENTATIVE DAVID W. MOSTROM November 11, 1999 Signed by Date 32339 Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE