LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Schoolcraft Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T41	-	
2. PROPERTY CONTROLL- 20 ING IN SECTION) ,T. 41 N. R. 16 W.	5,7	
3. MISCELLANEOUS PROPERTY IN SECTION	,TS., RE.		
4. LOT NO , REG	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re and rules therefore as required Bureau of Land Management o and 5 above were, in a field sur	e-monumented, recovered or re in the current manual of surve r by a decree of a court of law.	stored as expressed below and by instructions of the United S. Furthermore, that the come 19, found, recovered, res	of P.A. 74, Michigan P.A. of 1970, 21-1, 1983, established in conformance with regulations states Department of the Interior points mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a
A. Description of original mon	nument and accessories and/or s	subsequent restoration:	•
5 North 1/16 Corner	of Section 20. Not p	rev. set.	
7 North 1/16 Corner	on Eastside of Section	n 20. Not prev. set.	
B. Description of corner eviden	nce found and/or method appli	ed in restoring or re-establishin	ng corner;
5 Corner set M.P.O.I	L. between North 1/4 c	orner and center corn	er of section 20.
7 Corner set M.P.O.	L. between N.E Sec. Co	or. and East 1/4 corne	r of section 20.
C. Description of monument for		_	
5" Cedar, N48°L,	rings: 6" Cedar, S15 8.7' & 1½" Pipe, N6	8°W, 30.6'.	
7 D.N.R. Mont. Bear 7" Cedar, N240E,	rings: 7" Cedar, N52 44.2' & 12" Cedar,	'W, 53.2' & 14" Tama 524°E, 80.7'.	rack, NO2 ⁰ E, 44.6' &
			and the same of
SIGNED BY Land	B. Ballitt	DATE 8-8-8	3
David I . Eat SURVEYOR'S MICHIGAN RE	costration NO 21558		(SEAL)
SURVETORS MICHIGAN RE	GISTRATION NU. 2.770		(====