

JAN 21 1999

SCHOOLCRAFT COUNTY  
PEER GROUP APPROVED  
DATE 12/2/98 TAB

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft Located In: Corner Code #  
(County)

1. Public Land Survey T41NR16W G3  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

SIGRID HEDBERG 1P  
SCHOOLCRAFT CO. REGISTER  
Page 1 of 1 LC 4/269  
JLO Rec. Date 12/28/98 Time 15:27  
REVENUE FEES: 9.00

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Thomas P. O'Brien in a field survey on Dec. 18, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G3 NW Corner Section 10, T41N - R16W  
Sept. 11, 1845 - John Burt D.S. set post corner of sections  
3, 4, 9 & 10 referenced by: Aspen 5 S69W 7 Y.Pine 18 N62E 34

March, 1996 - James H. Moore RLS 28423 indicates " No evidence of corner was found at the position indicated on mentioned survey map by Bill Bowman. I monumented the corner based on the bearings and distances given on Bill Bowman's survey of record."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G3 Dec. 18, 1998 - Thomas P. O'Brien P.S. recovered 5/8" x 30" rebar stamped 3, 4, 9 & 10. Existing witnesses verify corner location as set by Moore RLS 28423 in march 1996. Replaced rebar with Schoolcraft County Monument stamped to identify.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G3 Schoolcraft County Monument stamped to identify. Repainted blazes on NBT's and made measurements to the following references:

8" Cedar - N14°E - 21.14'  
12" Hemlock - N67°E - 35.79'  
6" Cedar - S25°E - 15.52'  
4" Maple - N57°W - 24.54'  
Carsonite post - North - 1.0'

Thomas P. O'Brien

Signed by Thomas P. O'Brien  
Surveyor's Michigan License No. 21274

Date December 20, 1998

