

FEB 08 2001

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

DATE 10/10/00 DB

SIGRID HEDBERG
SCHOOLCRAFT CO. REGISTER
LC 4/363
Time 11:53:01
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74 Mich. P.A. 1970

SECTION
1P

For corners in

Schoolcraft
(County)

Located In:

Corner Code #

SIGRID HEDBERG
SCHOOLCRAFT CO. REGISTER
Page 1 of 1
JLV Date 12/19/2000
Time 11:53:01
1P

1. Public Land Survey

T 42N R 14W I1 ✓
T 43N R 14W I13

2. Property Controlling
in Section

S T R
S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R
S T R

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Thomas P. O'Brien, in a field survey on 10/9/00 xx do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Oct.20, 1850 Algernon Merryweather, DS section corner Sections 2,3
Tamarack 7 in S70W 10 links Spruce 6 in North 5 links Tamarack 14 N44E 19 do 10 N45W 23

Sept.15, 1961 Billy D. Buckler, RLS "This corner was re-established by single proportionate measurement between $\frac{1}{4}$ corner $\frac{1}{2}$ mile west and Section Corner 1 mile East. No original evidence.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Oct.9, 2000 Thomas P. O'Brien, PS found Mich. Dept. of Cons.cap on pipe as set by Buckler and verified by witnesses and distances to corners E and W. Accepted corner as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Michigan Department of Conservation cap on pipe.
Witnesses:
12" Cedar N59°E 24 links- exsisting Buckler BT.
10" Cedar S76°W 15 links- exsisting Buckler BT.
6" Cedar N41°W 19.40'
4" Cedar S56°E 23.15'
Carsonite Post North 1.0'



Signed by Thomas P. O'Brien
Surveyor's Michigan License No. 21274

Date Dec.12, 2000

LIBER 4 PAGE 363