

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 42N R 15W	F2
	S 4 T 42N R 15W	12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5				3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 05/02/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F2) Center of Section 4. Not established in the original survey. Found no subsequent record.

(12-Sec. 4) South 1/16 corner, Sec. 4. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F2) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners. From the position thus established, I found a squared wood post N40W 10 ft. distant, which I did not accept as marking the position for the corner.

(12-Sec. 4) Established the position for the corner midway and on a straight line between Quarter corner 1320.59' south and the Center of Section 4 1320.59' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F2) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
20" Y.Birch N37E 22.2' mrkd "CS BT"
5" Sugar S73E 29.1' do
17" Sugar S83W 34.75' do
6" Sugar N47W 23.5' do
E= 8062793.042 N= 142590.492

(12) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
22" Maple N60E 16.9' mrkd "S1/16 BT"
17" Maple S58E 23.3' do
17" Maple S22W 26.3' do
7" Sugar N36W 7.1' do
E= 8062800.691 N= 142188.100

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID DL6164: N= 131822.939 m. E= 8059239.498 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/05/2013

For the Michigan Department of Natural Resources, Forest Resources Division

