

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 17 T 43N R 16W	12
	S 7 T 43N R 16W	5
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Stephan J. Szyszkoski, in a field survey on 12 10/25/2011
5 05/31/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 17) South 1/16 corner, Section 17. Not previously monumented.

(5-Sec. 7) North 1/16 corner, Section 7. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 17) Established the corner position midway and on a straight line between Quarter corner D7
1325.92' south and the intersection of 1/4 lines of Sec. 17 1325.92' north. Note: The monuments for
Government corners C6, E6, and D7, placed in 2007 for Schoolcraft County Remonumentation, were
discovered to have been placed in erroneous positions. The position for the 1/16 corner herein
described was calculated using the proper positions for these corners, based upon the method of
reestablishment described in the certificates of record, L5 P453 and L5 P397. Schoolcraft County
Remonumentation has expressed their intention to correct the positions of the monuments for C6, E6,
and D7.

(5-Sec. 7) Established the position for the corner midway and on a straight line between Quarter
corner B3 1323.50' north and the intersection of 1/4 lines of Sec. 7 1323.50' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Tamarack N32W 15.6' mrkd "S1/16 BT"
7" Tamarack N46E 13.15' do
7" B.Spruce S21E 27.75' do
9" Cedar N73E 23.35' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(5) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Cherry S33E 38.25' mrkd "N1/16 BT"
8" J.Pine N50E 71.2' do
11" R.Pine N61W 80.7' do
6" J.Pine S31W 38.4' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/27/2012

For the Michigan Department of Natural Resources, Forest Resources Division

