

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T43N R 16W	M5
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File  
Number

I, Stephan J. Szyszkoski, in a field survey on Oct. 25, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
(M5) Corner common to Sections 12-13 T43N-R16W and Sections 7-18 T43N-R15W. 1841 - Established by Wm.A.Burt, Deputy Surveyor. Set post. Bearing trees: Fir 7 N23W 33 links, Tamarack 8 N54E 27 links. 1850 - Additional bearing trees by A.Merryweather: Spruce 4 N3E 5 links, Cedar 6 S34E 40 links. 1969 - Frank J. Bray RLS reestablished the corner by single proportionate measurement to the original record between Section corners 1 mile north and south. Set 1" iron pipe with 4" aluminum cap. New bearing trees: 5" Cedar N68W 19.5 links, 8" Cedar N48E 21 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
(M5) Found the 1969 monument in good condition and at record bearing and distance from the 1969 witnesses, both in good condition. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
(M5) Found 1"ID I.pipe with 4" alum. State of Michigan cap. Set measuring nail with MDNR tag in the side of:  
9" Cedar N66W 13.02' mrkd "S12" (1969 NBT)  
10" Cedar N50E 14.4' "S7" do  
10" Cedar S58E 10.15' "S18 NBT"  
8" Cedar S71W 28.90' "S13 NBT"  
Set carsonite post 1.0' north.  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 11/1/07

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS