LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	v corners in	Little trademantions of Not 14' wich			
_	County	Located In:			Corner Code ##
	Public Land Survey	т	46N _{FR}	14W	K7

Property in Sec.

expressed below:

Register of Deeds Stamp & File Number

4. Lot No. ______, Recorded Plat _______

5. Private Claims ______

I, Stephen J. Szyszkoski , In a field survey on February 63, 1994 , 19 do hereby certily that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

2 6 5 4 3 2 3 3 4 5 5 6 18 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13

A. Description of original monument and accessories and/or subsequent restoration:

Bection corner common to Sections 13-14-23-24. Corner resetablished and monumented in 1982 by Billy D. Buckler, RLS, as follows:
Placed 1° pips with 4° brass cap, corner reestablished by double proportionate measure from corners 1 1/2 miles Morth, 2 miles South, 1 mile East, and 3 miles West. No evidence of original corner. Witnesses: 12° Jack pine 840E 21.5 links, 7° Jack pine 880W 19.5 links, 10° Jack pine M45W 25.5 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered Buckler's monument as described, at record bearing and distance from all three Jack pine MBTs, now dead. Cut off the three trees above the scribed SN blaze so that they would not blow over, and marked two new bearing trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1° pipe with 4° Mich. Dept. of Conservation cap. Slezed, scribed, and set measuring nails in the following new bearing trees: 12° Jack pine MOSM 49.4° "\$14 MBT" 14° Jack pine \$63E 79.9° "\$24 MBT"



Signed by Stephen J. Szypykoch.

Date _____3-15-9-

IM APPROVED BY MICHIGAN STATE SOARD OF LAND SURVEYORS, JAN. 28, 1871. REVISED MAY 14, 1875.