LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Schoolcraft	Located In:	Corner Code #		
(County)				
1. Public Land Survey	T 46N R 14W			
2. Property Controlling in Section	S T R R S T 46N R 14W	9	O	
3. Miscellaneous	S T R			
Property in Sec.	S		Register of Deeds 5	Stamp & File Number
4. Lot No. , Re	corded Plat		Troglotor or Decease	stamp of the Homber
5. Private Claims	-		ABCDEF	GKIJKL
	12 04/	07/2010	2 - 6 - 5 6	300-2
ı, Stephan J. Szyszkoski , i	in a field survey on 9 04/2	28/2010 do hereby state	3	
that under requirements of P.A.	74, Michigan P.A. of 1970, the corner		₂⁴├─ ┆─┼─₿─┼─	10-11-12-
above were in conformance with	regulations and rules therefore as requir	ed in the current manual of survey	,5	
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6				6-15-14-13-
	corner points mentioned in lines 3, 4 and			
the rules of the Michigan Boar	B 19 20 2	222324		

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

(I2) Quarter corner common to Sections 2 and 3. 1850-Established by Guy Carleton Deputy Surveyor. Set post. Y.Pine 10" S8E 13 links, Y.Pine 8" N65W 05 links. 1956 - Recovered by Billy D. Buckler RLS: Found 2" iron pipe with brass cap set by Carl Christianson, Manistique. Two Yellow Pine B.T.s in excellent condition. New BTs: 9" R.Pine SO2E 32 links, 9" R.Pine N39E 58.5 links.

(9-Sec. 3) East 1/16 corner, Section 3. Not established in the original survey.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (I2) Found a 2" iron pipe with brass cap stamped "C.C." at record bearing and distance from the original B.T. Y.Pine N65W 5 links, found standing dead with blazes plain. The Y.Pine BT SE was not recovered. Also at record bearing and distance, the two 1956 R.Pine NBTs, in good condition. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(9-Sec. 3) Established the corner midway and on a straight line between Center of Section 1319.96' west and Ouarter corner 1319.96' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I2) Fd. 2" I.pipe with brass cap. (9) Set 1"IDx36" I.pipe w/4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 12" R.Pine S06W 21.45' mrkd "1/4S" 1956 NBT 13" J.Pine S71W 7.5' "E1/16 BT' mrkd 12" R.Pine N47E 39.0' do do 11" J.Pine S49E 19.15' do 8" R.Pine S70W 4.65' mrkd "1/4S NBT" 17" R.Pine N34E 21.55' do 6" R.Pine S83E 16.9' 5" J.Pine N18W 37.6' do do Bearings are magnetic. Bearings are magnetic.

Surveyor's Michigan Licénse No.

Date 12/01/2010 STEPHAN J YSZKOSK

OF MICH

LAND

ISSURVEYOR

For the Michigan Department of Natural Resources and Environment, Forest Manageme

47433

FORM APPROVED BY MICHIGAN STATE BOARD

47424