

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft

(County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 15W

J3

T R

T R

S T R

2. Property Controlling
in Section

S 3 T 46N R 15W

2

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Jun 07 2006

I, Stephan J. Szyszkoski, in a field survey on _____, 20 ____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J3) Quarter corner common to Sections 2 and 11. 1976 - Reestablished by Herbert Fluarty RLS midway between Section corners. Set 5/8"x18" iron with cap. 6" J.Pine N34E 30.27', 6" J.Pine S44E 40.44', 12" J.Pine S65W 57.04'.
(2-Sec. 3) East 1/16 corner between Section 3 T46N-R15W and Section 34 T47N-R15W. 1964 - Established by F.J.Bray RLS midway and on line between 1/4 corner to West and Section corner to East. Set 1" iron pipe with 4" aluminum cap. 10" Beech N74E 17 links, 8" Beech S19W 43 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J3) Recovered the 1976 monument in good condition, buried on the east side of a N-S road and at record bearing and distance from the remaining 1976 witness tree J.Pine NE, in good condition. The monument is 8.26' north of a straight line between Section corners and 0.34' West of the midpoint. Accepted the monument as found.

(2-Sec. 3) Recovered the 1964 monument in good condition and at record bearing and distance from the remains of the 1964 NBT Beech SW, now a stump. The Beech NE was not recovered. My measurements show that the monument is located 0.80 feet from the midway position intended in 1964 and I accept the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J3) Found 5/8" pin with plastic cap.

Set measuring nails in:

14" J.Pine N39E 30.2' mrd "1/4S NBT" *

10" Tamarack N02E 35.9' do

8" J.Pine N79W 47.1' do

9" J.Pine S78E 71.65' do

Bearings are magnetic. Distances are to nail with tag. * denotes 1976 NBT.

(2) Fd. 1" I.pipe with 4" alum. MI Dept.

of Conservation cap. Set measuring

nails in:

9" Maple S72E 6.08' mrd "E1/16 BT"

12" Hemlock N81E 31.44' do

6" Maple N34E 24.1' do

12" Y.Birch N66W 15.42' do

Bearings are magnetic. Distances are to nail with tag.



Signed by

Stephan J. Szyszkoski

Surveyor's Michigan License No.

33986

Date

8/15/06

For the Michigan Department of Natural Resources, Office of Land and Facilities