Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 16W

	Sc h	colcraft Coun
DESCRIPTION OF CORNER	Section Corner for Sections 2-3-10-11	
CORNER MONUMENT	l" Pipe with 4" Brass Cap.	
DATE MONUMENT PLACED AND WI	TNESSED 9-12-61	
_	8" Cedar (S11 NBT) S460	12 links
N -	9" Cedar (S2 NBT) N36°	32 links
_	9" Cedar (S3 NBT) N77° W	7 17 links
A	0	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one tamarack B.T. bearing S45°E 09 links. Tamarack down and in poor condition. Scribe marks plan. Corner lies in Cedar swamp.

SURVEYOR'S SEAL

SIGNED SIGNED LAND SURVEYOR
Billy D. Buckler