

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 16W T 46N R 16W T R	G6 H7
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on H7 02/07/13
G6 06/11/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G6) Quarter corner common to Sections 15 and 16. 1954 - Dean C. DeLaMater RLS remonumented the
corner from one original B.T., down, in good condition. Set 1" pipe with 4" brass cap. 12" Hemlock
S68°W 22 links, 10" Hemlock N23°E 39 links.

(H7) Quarter corner common to Sections 15 and 22. 1954 - Dean C. DeLaMater RLS remonumented the
corner from two original B.T.s, still in place, one in good condition, one poor [W.Pine 30" N48°E 52
links, Y.Birch 12" N48°W 16 links]. Set 1"ID iron pipe with 4" brass cap. NBTs: 10" B.Cherry N04°W
18 links, 18" Hemlock S77°E 42 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G6) Found the 1954 monument in good condition and at record bearing and distance from the 1954
NBTs. The Hemlock SW is in good condition, the Hemlock NE is down on the ground. The original BT
W.Pine 24" S63°E 6 links is present at record bearing and distance, now a tipped up stump. Accepted
the monument as a careful and faithful perpetuation of the position of the original corner.

(H7) Found the 1954 monument in good condition, at record bearing and distance from the 1954
accessories, the B. Cherry in good condition and the Hemlock standing dead. The original W.Pine BT
NE is at record bearing and distance, now a stump with no markings visible. Any trace of the 2nd
OBT would be obscured by deep snow at this time. Accepted the monument as a careful and faithful
perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G6) Found 1"ID I.pipe with 4" brass MI Dept. of
Conservation cap. Set measuring nail with MDNR tag
in the side of:
15" Hemlock S72°W 14.6' mrkd "1/4S" 1954 NBT
6" Cedar N64°W 8.5' mrkd "1/4S NBT"
5" Maple S10°E 17.15' do
5" Maple N50°E 17.6' do
E= 8053579.361 N= 177984.448

(H7) Found 1"ID I.pipe with 4" brass MI Dept. of
Conservation cap. Set measuring nail with MDNR
tag in the side of:
14" B.Cherry N01°W 11.95' mrkd "1/4S" 1954 NBT
9" Sugar N48°E 7.65' mrkd "1/4S NBT"
10" Hemlock S06°W 19.4' do
10" Maple S87°W 24.0' do
E= 8054386.855 N= 177181.450

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RK0046: N= 173923.068 m. E= 8052746.340 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/10/2013

For the Michigan Department of Natural Resources, Forest Resources Division

