

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 16W

Schoolcraft COUNTY


DESCRIPTION OF CORNER $\frac{3}{4}$ Corner for sections 18

19

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-21-61

WITNESSES TO CORNER..... 8" Cedar in clump (NBT $\frac{1}{4}$ S) S 60°W 27 links



11" Cedar (NBT $\frac{1}{4}$ S) N85°E 16 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from Tamarack stump (rotted) at proper bearing and distance point of wood post was found in wet muck. Squared tree found chopped down 01 $\frac{1}{2}$ links south of corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 29, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler