## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 47M N.R. 16M

Schoolcraft COUNTY

DESCRIPTION OF CORNER North east 1/16 corner, Sec. 12

CORNER MONUMENT 1<sup>M</sup> pipe with 4<sup>M</sup> aluminum cap

DATE MONUMENT PLACED AND WITHESSED 11-6-69

WITHESSES TO CORNER. 12<sup>M</sup> Tamarack (1/16 BT) N6<sup>®</sup>E 25.9

N 7<sup>M</sup> Cedar (1/16 BT) S5<sup>®</sup>E 27.5<sup>‡</sup>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This cerner placed at intersection of lines connecting opposite 1/16 cerners on the NE quarter of Section 11, according to B.L.M. rules for section sub-division.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

Billy Q. Buckler.

SIGNED Billy D. Buckley

DATE 1-26-70

REGISTERED LAND SURVEYOR