

61

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T. 47N R. 16W 15

T. 47N R. 16W 15

T. R.

T. R.

2. Property Controlling
in Section

S. T. R.

S. T. R.

3. Miscellaneous
Property in Sec.

S. T. R.

S. T. R.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Nov 14 1995

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

(15) Corner common to Sections 10-11-14-15. Corner perpetuated and monumented in 1952 by Dean C. DeLaMater, RLS, from an original bearing tree. Corner monument: 1" pipe with 4" brass cap. Witnesses to corner: 14" Beech N54E 31 links, 14" H. Maple S20E 13 links.
(35) Quarter corner common to Sections 11-14. Corner reestablished by proportionate measurement in 1954 by Dean C. DeLaMater, RLS. Corner monument: 1" pipe with 4" brass cap. Witnesses to corner: 12" Hard Maple N20W 26 links, 12" Hard Maple S08E 84 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15) Found the 1952 monument as described, in good condition, and at record bearing and distance from the stumps of both 1952 witness trees, which have been cut. Left the monument in place and marked four new trees as described below. Corner witnessed by T. Stark and D. Laapela, Newberry.
(35) Recovered the 1954 monument as described, in good condition, and at record bearing and distance from the remaining witness, a 15" Sugar S06E. The other witness had been cut. Left the monument in place, placed a measuring nail in the 1954 witness, and marked three new accessories as shown below. Corner witnessed by T. Stark and D. Laapela, Newberry.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Found 1" iron pipe with 4" brass Mich. Dept. of Conservation cap. Blazed, scribed, and set measuring nails in the following:
10" Maple N22W 15.0' "S10 NBT"
4" Hemlock North 16.8' "S10 NBT"
10" Maple N30E 30.7' "S11 NBT"
4" Hemlock S30E 4.95' "S14 NBT"
Placed a 4" scribed cedar post adjacent. Put location post/tag 55' north at S. edge of road. Bearings are magnetic.

(35) Found 1" iron pipe with 4" brass Mich. Dept. of Conservation cap. Blazed, scribed, and set measuring nails in the following:
15" Sugar S06E 55.85' "1/4S"
14" Sugar N28E 8.65' "1/4S NBT"
5" Beech N52W 10.4' "1/4S NBT"
8" Beech S17W 52.85' "1/4S NBT"
Placed a cedar post adjacent. Corner is approx. 20 ft. north of C/L road. Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12-11-96

For the Michigan Department of Natural Resources - Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1988