SURVEY & REMONUMENTATION

DEC 1 5 1993

Miscellaneous

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE

RECORDED

COMMISSION Filing	Requ	iremen	t of	Act	74	Mic	h. P.A	. 1970

93 DEC - 6 AM (0: 58

or corners in REMONUMENTATION Located In: hiawassee Corner Code =## T 5N R 2E M-13 Public Land Survey T _____ R __ Τ. R Property Controlling S _ _ T ____ R . in Section S __ _ T ____ R .

_ T .____ R _

__ R .

REGISTER OF DEEDS Layer Flendin SUBSSICETT COURTY HIGH.

Register of Deeds Stamp & File Number

___ , Recorded Plat _ Private Claims __

_ T _

Norman C. Caldwell . . in a field survey on November o hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned h lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land fanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

Description of original monument and accessories and/or subsequent restoration:

-13 Twp. cor. common to T4 & 5N - R2E & T4 & 5N - R3E

Wood post placed by J. Wampler, 1826 West 136 lks. (89.76') 6" Tamarack N34°E 94 lks. (62.04') 4" Tamarack

Survey by E. F. Joslin, Co. Surveyor, Feb. 1900, recorded in Book E., pgs. 246 & 247, S.C.R., in marsh, Book E., pg. 184, the post at twp. cor. had been destroyed by fire. I relocated it by putting it in line with a wire fence said to have been built from it & on the testimony of Fred Wilkinson. The ground is covered with water at that place.

Survey by M. L. Varaemdonck, Sept. 1988, recorded in Surveys L. 5, pg. 144 & L. 5, pg. 359 Fnd. 3/4" pipe
East 20.15' W. face N. leg arrow sign N20°E 68.20' SW. cor. R.R. tie post N50°W 50.40' SE cor. tele. cable cabinet

\$60°W 49.55' W. face stop sign post

Unrecorded survey by L. A. Bryan, Dec. 1992

Fnd. 3/4" pipe N50°E 19.10' N & T #25832 S. side 14" Elm 880°E 38.02' N & T #25832 N. side 12" Box Elder S50°E 26.91' N & T #25832 N. side 6" Box Elder

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

-13 Twp, cor, common to T4 & 5N - R2E & T4 & 5N - R3E

Fnd. $3/4^{\circ}$ pipe per L. 5, pg.s 144 & 359 of Surveys and unrecorded Bryan Survey. Ingham Co. Remon. 1975, previously dug a hole at this location and fnd. no additional evidence. We dug a 10° x 16° x 4° deep (2° below orig. ground) on the Co. Line and immediately West of existing pipe, fnd. no evidence of 1900 Co. Survey. Held record 3/4" pipe, replaced with a standard 20" Harrison marker as approved by Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

of the corner:

713

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Twp. cor. common to T4 & 5N - R2E & T4 & 5N - R3E

Fnd. 3/4" pipe per L. 5, pg.s 144 & 359 of Surveys and unrecorded Bryan Survey. Ingham Co. Remon. 1975, previously dug a hole at this location and fnd. no additional evidence. Ind. 3/4" pipe per L. 5, pg.s 144 & 359 of Surveys and unrecorded Bryan Survey. Ingham Co. Remon. 1975, previously dug a hole at this location and fnd. no additional evidence. We dug a 10' x 16' x 4' deep (2' below orig. ground) on the Co. Line and immediately West of existing pipe, fnd. no evidence of 1900 Co. Survey. Held record 3/4" pipe, replaced with a standard 20" Harrison marker as approved by Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

E8510 N ZONOU

CALDWELL PROFESSIONAL SURVEYOR

No. 12018

ned by veyor's Michigan License No.

では

reer keview Group and is accepted as the best available evidence of the position of the original corner.

N65°E 19.14' Fnd. N & T #25832 \$. fc 20" Elm (R)

N20°E 68.19' Set N & T W. fc R.R. tie Cor. Post (R)

N50°W 31.12' Chis. "+" top center W. end CMP

\$80°E 20.14' N. leg traffic arrow sign (R)

Date

Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

12018