SUNVEY & CONUMENTATION

. APR 0 8 1996

I AND CORNER RECORDATION CERTIFICATE Mich. P.A. 1970

For corners in	Filing	ı Requirement	of.	Act	74,	N
For corners in						

Corner Code # Located in: Shiawassee (County) T 8N R 1E (K-11) 1. Public Land Survey Ŧ 2. Property Controlling In Section 3 Miscellaneous Property in Sec. Recorded Plat 4. Lot No. 5. Private Claims

Laye Hudda Register of Deeds Stamp & File Number

RECORDED

95 NOV 22 PM 1: 19

REGISTER OF DEEDS

I. Mark L. VanRaemdonck, in a field survey on October 12, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1.) Original: R.Thomas, D.S., 1831 Monument: Wood stake

Accessories: Birch 10 N29°W 36

do 3 \$40°E 50

2.) V.W. Royce, Co. Surveyor, 10/31/1912, Road Book 1B, page 1&2

Monument: Iron at corner

Accessories: W. Ash 6" S361/2°W 70 links

3.) O.M. Elliot, Co. Surveyor, 6/23/62, Book 39, page 34

Monument: Not given

Accessories: Road sign NW 46.5

SW corner church NE 69.7'

4.) O.M. Elliot, Co. Surveyor, 1959, Book 31, page 78

Monument: Not given Accessories: SW corner of church NE 69.8*

5.) J.F. Quine, Field Book #16, page 87, 8/10/71

Monument: Found 3/4" iron pipe flush, verified by old recorded bearing tree

2 3 4 5 6 7

12 Accessories: Ash 40" (old BT) S42°30'W 47.2" Power Pole S31°E 45.6' SW corner church foundation NE 69.75' Road name sign post NW 46.4'

6.) J.F. Quine, L.C.R.C. recorded Liber 1, page 506, 3/11/75 Monument: Found 3/4" Iron pipe

Accessories: Same as no. 5 above

7.) J.F. Quine, Survey recorded Liber 2, page 344, May 1976 Monument: Found 3/4" pipe stake verified by old bearing tree

Accessories: None given

8 9

10

11

30

8.) J. F. Quine, Survey recorded Liber 6, page 885, 7/8/94 Monument: Found "T" bar in Monument Box Accessories: Refers to L.C.R.C. recorded Liber 1, page

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found "T" iron in Monument Box. Verified location by measurement to references in no. 5 above. Also found stump that was called for by Royce in no. 2 above. This location also fits ties given by O.M. Elliot in no. 3 above. Found no conflicting evidence. Excavation for Harrison Marker provided no further evidence. Accepted this location as the careful and faithful perpetuation of the original corner location.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Replaced "T" iron with standard Harrison Marker stamped "Remon 24622" and is witnessed by the following accessories:

S30°E 45.28' Set N&T #24622 in W. face utility pole N45°E 62.29' NW corner brick planter box at Carland U.M. church

N45°W 46.15' SE face 2½ steel pipe road sign post S60°W 59.92' Top cen. tele. cable box

APPROVED

County Remonumentation

Peer Review Group 09 24, 1995 INLV

MICHIGANIN OF MICHIGAN MARK L. VANRAEMDONCK LAND SURVEYOR No. 24622

Surveyor's Michigan License No. 24622

M APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN 18, 1971 REVISED MAY 14, 1975 REVISED JAN, 1983