APR 0 5 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in	· mig madana	"	SEQUENCE #	2
Wayne	Located In:	Corner Code ##		375
(County)	Van Buren	Come Code	LIBER 28471 PAGE) (3
1. Public Land Survey	T R T R	B-3	Compliance with ACT 345, P.A. 1990	
Property Controlling in Section Miscellaneous	TR TR STR STR	Seg 2	APPROVED ON: 12-12-95 F. WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Num	ber
Property in Sec.	\$ T R			
4	December 101st			
·	Recorded Plat		ABCDEFGHIJ	KLI
5. Private Claims			2 5 5 4 3 1 2	4 -
		•	3	
\$32500 YS 1 31	Dagamb	er 5 95	4 - 7 - 1 - 8 - 1 - 9 - 10 - 11	12-
	, in a field survey on		. 5	
	equirements of P.A. 74, Michigan P.A. o			ı——— 13-
	in conformance with regulations and ructions of the United States Departn			
	f a Court of Law and/or that the corner			
	ith the rules of the Michigan Board of			
The state of the s	re-established, monumented, re-m	onumented, recovered, found as	s	
expressed below:	#		20 20 20	25
	corners, all in the same town and	i range, may be recorded		
on this certificate	3.	•	12 -31 -32 -33 -34 -35	5-1-36-
B-3) South corner secti G.L.O. (1830's) J. Wan W.P.A. (1930's) found a S.E. 33.83 Tel pole (gon WCRC no witnesses for	ne), N.E. 72.20 20" Apple (gone),	ownship Im 11 S. 10 W. 12 (gone), Suga B" Maple (gone), S.W. 69.22 1 N. 35.72 6" Locust (gone).	ar 9 N. 12 W. 18 (gone). 14" Elm (gone), S. 31.21 36" Maple (go	952713
				9
B. Description of corner	evidence found and/or method a	oplied in restoring or reestablis	shing corner:	,—
Found a 1" steel bar in Verified corner locatio C-3 to C-2 Record = 2	on 6, T.3 S, R.8 E., Van Buren To the centerline of Ecorse Road (and by comparing W.P.A. survey we 668.52 Measured = 2668.68 690.04 Measured = 2689.85	isphalt) . Eastalled a monumer	\$ 4.00 REMDINUMENTATION \$ 7.00 DEED	
	to C-3 and C-2 Record = 89° 44°	10" Measured = 89° 44' 03"	19 DEC 95 11=54 A.M. RECEI RECORDED	A
			FOREST E. YOUNGBLOOD, REGISTER WAYNE COUNTY, MI	EDS

Description of monument for corner and accessories established to perpetuate locating the position of the corner: B-3) South corner section 6, 1.3 S, R.6 E., Van Buren Township

Found a 1" steel bar in the centerline of Ecorse Road (asphalt). Installed a monument box and cover.

The selected location is accepted by the contractor and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

Date _/2-14

WITNESSES:

Set Top bolt of hydrant N. 52° E. distance = 67.31

Set steel bar S. 22° E. distance = 50.21

Set nail and WCR tag South face 24" Maple cluster N. 71° W. distance = 76.06

Set nail and WCR tag East face 15" Maple N. 22° W. distance = 28.94

Placed Wayne County Remonumentation brass marker and cap #10705

igned by WWW Joshu Co urveyor's Michigan License No. WILLIAM L
* ROCKELLY
LAND STRVEYOR
NO.
10705

4K 7D

TE BANKA F LAND SORVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAM., 1963