LIDER 18952 PG 315

For corners in	
Oakland	
(County)	
1. Public Land Survey	

AND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970	\$ 9.00	MISCELLANEOUS	RECORDING
		X REMONUMENTAL	

	ited In: Comer Code #	
(County) Wes	t Bloomfield Township	
1. Public Land Survey	T <u>2N</u> R <u>9E</u> <u>G-6</u> T R	
2. Property Controlling S	TRANSPARENT	
3. Miscellaneous S	TR	ő
4. Lot No, Recorded Plat	SECTION	
5. Private Claims		2

Compliance with ACT 345, P.A. 1990 9-16-58 PPROVED ON: AKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE

LYNN D. ALLEN, CLERK/REGISTER OF DEE

16 SEP 98 7:37 A.M.

PAID

8

~

RECEIPTE MA

RECORDED - CIAKLAND GOON

Register of Deeds Stamp & File Numb

, 19<u>98</u> o hereby state that under i, Huston K. Kennedy _, in a field survey on <u>June 12</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- 6 7 q 10
- Description of original monument and accessories and/or subsequent restoration: 1817-GLO Carpenter, D.S.; No post was set 1979-"ORCHARD WOODLANDS", Liber 176, pages 8 & 9
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998-Kennedy Surveying, Inc. -- Kennedy, PS #17623 -- The corner falls in Upper Straits Lake.

HOW THE CORNER WAS RECOVERED

Based upon the description of "ORCHARD WOODLANDS" a plat recorded in Liber 176 of plats, on pages 8 & 9 of Oakla County Record. I was able to calculate the position of the corner which is inaccessible corner that falls in Upper Straits La and established two (2) meander corners on the East-West 1/4 line of Section 15.

FIELD MEASURMENTS BETWEEN

G-6 to G-5 No GLO, corner falls in Upper Straits Lake 2671.00 Ft. (GPS-CAL-MEA)

G-6 to G-7

No GLO, corner falls in Upper Straits Lake
"ORCHARD WOODLANDS (Sec 15) = 2641.65 Ft. (PLAT CAL.) 2639.37 Ft. (GPS-CAL-MEA)

FRCFESSIONAL SUME PROFESSIONAL STREET C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-6 I placed a 2" diameter brass cap stamped Oakland County Remonumentation, PS #17623 on the found 4" diame Concrete Monument as a meander corner to G-6

N03"W 13.73' Set Mag Nail, & Remon Washer West face 26" Hickory

S86°W 469.35 Ft. to G-6 (inacessible corner)

N31°E 13.79' Set Mag Nail & Remon Washer SE face 12" Oak Due East 52.92' Set Mag Nail & Remon Washer South face 34" Ash S27°W 6.26' Set Mag Nail & Remon Washer East face 24" Oak

The selected location is accepted by me and is generally accepted by Profithe position of the original corner based upon "ORCHARD WOODLANDS".	lessional Surveyors as the best available evidence
the position of the priginal corner based upon "ORCHARD WOODLANDS".	
	•

signed by Just 4-1	-4	Date 7/29/98	
jurveyor's Mickense License No.	M6Z3		,

THE OF MICH, THE OF MICHIGAL

HUSTON KENNEDY

PROFESSIONAL SURVEYOR

17623