

FEB 24 2000

SECTION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

99 OCT 27 PM 1:48

Ray [Signature]
REGISTER OF DEEDS
OTTAWA COUNTY MI

For corners in Ottawa _____ (County)	Located In:	Corner Code #
1. Public Land Survey	T5N ___ R15W ___	G-12
	T ___ R ___	West 1/4 corner
	T ___ R ___	Section 34
	T ___ R ___	Holland Township
2. Property Controlling in Section	S ___ T ___ R ___	
	S ___ T ___ R ___	
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	
	S ___ T ___ R ___	

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Steve Lampen _____, in a field survey on September 14, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-12	LCRC, L2, P29 - Clapp - 1973	LCRC, L5, P 285 - Brintnall - 1987
GLO - Brookfield - 1832	Found monument box	Found 1" pinched iron, set C.I.M.
Set 1/2 mile post	Power pole NW 35.90	SE 66.78 SW corner transformer box
Sugar 4 S 79 E 16	Power pole NE 42.50	ESE 64.08 PK E end top C+G rad.
Sugar 14 S 69 W 23	Guy pole SW 35.30	ENE 59.78 PK E end top C+G rad.
	Centerline street sign SE 47.0	NE 59.01 PK SE side power pole
		NW 49.48 PK in top C+G
		SW 47.31 tag in SE side power pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-12 Found cast iron monument in monument box.
NE 59.01 PK SE side power pole, SW 47.31 tag SE side power pole

Found cast iron monument fits the monumentation of many surveys and is accepted as a careful and faithful perpetuation of the position of the original corner.

RA. 005 OTTAWA COUNTY

9/20/99
[Signature]

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12 Cast iron monument in monument box		
Azimuth = Michigan State Plan grid direction		
Remonumentation tag in SE side power pole	37° 52'	59.13
Remonumentation tag in SE side power pole	213° 39'	47.66
SE corner building, concrete block	299° 32'	124.40
SE corner building, wood	220° 19'	75.28
SE corner building, brick	192° 49'	224.22
NW corner building, brick	240° 24'	114.82



RECEIPT #61/07

Signed by Steven Lampen Date OCTOBER 16, 1999

Surveyor's Michigan License No. 37279