LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_		
FOR	COTDET	t in

Not previously monumented.

Baraga (County)	_ Located In:	Corner Code #						
1. Public Land Survey	T R R T R T R R T R R T R R T R R T R R T R R T R							
 Property Controlling in Section Miscellaneous Property in Sec. 	S 30 T 48N R 33W S T R S T R S T R S T R	3 (GCDB 100260)	Doc-	:-A 5 P		0.5		
1, Stephan J. Szyszkoski , in that under requirements of P.A. above were in conformance with instructions of the United States a Court of Law and /or that the conformance with t	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require Department of the Interior, Bureau of Lacorner points mentioned in lines 3, 4 and	ed in the current manual of survey and Management or by a decree of 5 above were in conformance with	A B 1 2	C D	E F	mp & File	I J	K L 1
the rules of the Michigan Board re-established, monumented, recover	d of Land Surveyors or by a Decree ered, found as expressed below:	of a Court of Law; established,	9 19	20-	-21-	22_	23	
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range,	, may be recorded	10 30	32	33	34_	35_	-36-
A. Description of original m	onument and accessories and/or s	subsequent restoration:						

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 30) North 1/16 corner between Section 30 T48N-R33W and Section 25 T48N-R34W.

(3-Sec. 30) Established the position for the corner midway and on the Range line between Section corner 1313.77' north and Quarter corner 1313.77' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Sugar N14°E 16.95' mrkd "1/16S BT" 14" Sugar S68°E 14.75' do 8" Sugar S14°W 18.7' do 4" Sugar N40°W 17.25' do Set sq'd cedar post adjacent.



Bearings are magnetic.

Signed by	Stephen J.	Insulat.	Date	10/27/2015
Surveyor's M	ichigan License No.	33986		

Revised Oct., 1995