SUHVEY& REMONUMENTATION

MAY 0 5 1997

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION Baraga Located In:	Corner Code #	RECEIVED FOR RECORD THIS 3RD DAY OF JANUARY, 1997 AT 10:30
(County)	Confer Code #	A.M. AND RECORDED IN LIBER 4
1. Public Land Survey T T T T	R 33W A10 **	OF LAND CORNER RECORDATION RECORDS ON PAGE 754.
2. Property Controlling S T	R	BARAGA COUNTY REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		ABCDEFGHIJK.LM
5. Private Claims		2 6 5 4 3 2 1
	Nov 07 1996	3
, Stephan J. Szyszkoski , in a field surve	y on 19 do hereby state that under	4 - 7 - 8 - 9 - 10 - 11 - 12
conformance with regulations and rules therefore as a	e corner points mentioned in lines 1 and 2 above were in required in the current manual of survey instructions of the	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan		6 -18 -17 -16 -15 -14 -13
Board of Land Surveyors or by a Decree of a C recovered, found as expressed below:	ourt of Law; established, re-established, monumented,	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the sam	e town and range may be recorded	9
on this certificate.	o town and range, may be received	10 30 29 28 27 26 25
		11
		12 31 32 33 34 35 36
	essories and/or subsequent restoration: and R34W and common to Sections 30 T48N-R33W ar ction 2540.00 Set Spruce Post qr. Section Cor 24 & 25". Found no subsequent record.	
·		12-18-96
		3///
		·
B. Description of corner evidence found and	or method applied in restoring or reestablishing cor	ner:
original bearing trees, both recovered. The pwaterlogged sphagnum moss. It is now a 3" diaby 12" long stump fragment with old blaze, overtree was recovered as a mound of distinctly discribed corners on the range line, both perpet deg. 11 min. 13 sec. E, 39.810 ch. distant (be	e original corner post, and at record bearing and ost was recovered rotted off at ground level but a. spruce post point in excellent condition. The regrowth, axe mark, and bottom of measuring note tark colored organic material surrounded by light that the colored corners, were found to be 500 detainings referenced to astronomic north). At the tuminum MDNR tablet, stamped "Michigan Dept. of	t well preserved below ground, in the 6" spruce bearing tree is now a 3" wide the plainly visible. The tamarack bearing ter colored moss. The two adjacent g. 09 min. 25 sec. W, 39.869 ch., and NOO position of the post, I placed a 1" I.D.
C. Description of monument for corner and a	ccessories established to perpetuate locating the po	sition of the corner:
aluminum cap. Blazed and scribed the		OF MICH
	This corner is also M10 in T48N-R34W.	STEPHAN J.
6" spruce N24% 8.6' "1/4S NBT" 3" spruce N87E 9.0' "1/4S NBT"		SZYSZKOSKI
8" spruce SI8E 13.3' "1/4S MBT" 8" spruce S33W 15.1' "1/4S MBT" 9 and a 3" squared curry part adjacent. No.		and a lower blad SURVEYOR indicated in
Bearings are magnetic.	Distances are horizontal (unless noted) and me corner to the inside of a notch cut into the t	easured from the

For the Michigan Department of Natural Resources - Forest Management Division

18, 1996

Date_