

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W	I1
	T 49N R 32W	L3
	T	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Stephan J. Szyszkoski, in a field survey on I1 05/19/2011
L3 11/10/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I1) Corner common to Sections 2-3 T49N-R32W and Sections 34-35 T50N-R32W. 1842 - Established by
Wm.A.Burt Deputy Surveyor. Set sugar post. Y.Birch 8" N24E 35 links, Y.Birch 12" N24W 26 links.
Additional BTs by Guy Carleton Deputy Surveyor, 1852: Sugar 6" S50W 48 links, Sugar 8" S43E 45
links. Circa 1942 - Norman T. Thompson RLS found OBTs Sugar 8" S43E 45 links, now 10"; Y.Birch 12"
N24W 26 links, now 16"; and Y.Birch 8" N24E 35 links, all noted as "OK". Mr. Thompson set balsam
post and made new witnesses: B.Ash 9" N11W 47.6', and Y.Birch 12" S81W 22.4'

(L3) Quarter corner common to Sections 1-12. 1852 - Established by Guy Carleton Deputy Surveyor.
Set post. Yellow Birch 5" S36E 27 links, White Birch 11" S78W 24 links. 1941 - Norman T. Thompson
RLS remonumented the corner at record bearing and distance from the Y.Birch OBT S36E 27 links, found
down on the ground. Set post. Made new BTs: Cedar 20" S32W 35', Spruce 12" N32E 14.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I1) Found a 3/4"ID iron pipe projecting 10" a.g., firmly set with a lean to the south. At record
bearing and distance, found the cut stump of Thompson's NBT Y.Birch S81W 22.4'. All of the other
NBTs as well as the potential remains of the original BTs have been destroyed by fairly recent skid
road construction. I accept the pipe as a careful and faithful perpetuation of the position of the
original corner.

(L3) Found a 1"ID Iron pipe with mushroomed top projecting 15" above ground at record bearing and
distance from the N.T.Thompson NBT Cedar S32W, now a stump with blaze visible and at record distance
from his NBT Spruce 14.5', with blaze visible. The record bearing of the spruce appears to be in
error. Found numerous other blazed trees near, as well as a Ford Motor Co. location poster dated to
1955 on a downed tree and a newer location poster nearby with several names and dates. The original
BT Y.Birch was not recovered. Accepted the pipe as a careful and faithful perpetuation of the
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I1) Found 3/4"ID iron pipe projecting 10" a.g.
Set measuring nail with MDNR tag in the side of:
5" Sugar N17W 11.9' mrkd "S34 NBT"
10" Sugar S60E 16.35' "S2 NBT"
11" Sugar S08E 18.7' do
12" Y.Birch S73W 31.95' "S3 NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.

(L3) Fd. 1"ID I.pipe w/ mushroomed top, 15" a.g.
Set measuring nail with MDNR tag in the side of:
6" Sugar N01E 12.8' mrkd "1/4S NBT"
11" Maple S74E 17.7' do
6" Maple S07E 7.85' do
5" Sugar N70W 11.95' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/27/2011

For the Michigan Department of Natural Resources, Forest Management Division

