

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W T 50N R 32W T _____ R _____	K1 K13 (same corner)
2. Property Controlling in Section	S _____ T _____ R _____ S _____ T _____ R _____ S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	31		32		33		34		35		36		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 08/23/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K1) Corner common to Sections 1-2 T49N-R32W and Sections 35-36 T50N-R32W. 1846 - Established by
Wm.A.Burt Deputy Surveyor. Set Sugar post. Sugar 14" N70E 18 links, Sugar 7" N41W 23 links. 1852 -
Additional witness trees marked by Guy Carleton Deputy Surveyor: Sugar 8" S51E 25 links, Sugar 9"
S74W 14 links. Carleton notes the mile between Sections 1 and 2 as 79.84 chains. 1942 - Norman T.
Thompson RLS field notes state that he recovered the BT Sugar in Section 35 [1852 BT] and set Balsam
post at the corner. Mr. Thompson marked two new BTs: Sugar 6" S75E 24.5', Sugar 6" N50W 23.4'. Mr.
Thompson chained south to K3 and noted that "this mile is 28' short of notes".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K1) Found a 1"IDx23" iron pipe, set firmly. Found no evidence of the original BTs or of Mr.
Thompson's 1942 NBTs. This pipe is 5237.30' north of monumented K3, or 32.14' short of the Carleton
1852 record, and is 5265.69' (GLO rec. 5280') east of a perpetuated original corner at I1. The true
bearing from K1 to I1 was found to be N89 deg. 54' 09"W. I accept the 1" iron pipe as the best
available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K1) Fd. 1"IDx23" iron pipe.
Set measuring nail with MDNR tag in the side of:
4" Sugar North 12.0' mrkd "S36 NBT"
5" Oak N78E 14.5' do
5" Sugar S20E 8.1' "S1 NBT"
6" Sugar S87W 9.2' "S2 NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 12/05/2011
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Management Division