## SURVEY & REMONUMENTATION

APR 2 6 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners	ın			_	_
Baraga	County)	Located in:	Corner Code ##	OF DECEMBER,	RECORD THIS 19TH DAY A.D. 1994 AT 9:00 A.N IN LIBER 4 OF LAND
1. Public La	and Survey	T R T R T R		CORNER RECORD	DATION ON PAGES
2. Property		T R T R		BARAGA COUNTY	REGISTER OF DEEDS
in Section 3. Miscellar Property	neous S _	T R T R		Register of De	eds Stamp & File Number
					DEFGHIJKL
				2 6 3	-5-4-4-3-4-2-4-1-
Michae	el Mileski	ield survey on	December 19	94 4 5	- 8 9 10 11 12-
in lines 1 and current manua Management of above were in Court of Law expressed be NOTE: Not	2 above were in confor al of survey instructions of or by a decree of a Court of conformance with the ru c; established, re-estab- low:	mance with regulations and the United States Depart Law and/or that the corneles of the Michigan Board (lished, monumented, re-research)	of 1970, the corner points mend rules therefore as require then tof the Interior, Bureauer points mentioned in lines 3 of Land Surveyors or by a Decimonumented. recovered. found range, may be recorded.	d in the of Land 7, 4 and 5 8 19 10 and as 10 30	-17 - 16 - 15 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 15 - 14 - 15 - 14 - 15 - 15 - 15
		ent and accessories and	d/or subsequent restorati	13 13 On:	
	_		5, T51N, R31W, on 5		THE RESERVE TO SERVE THE PARTY OF THE PARTY
	See back of form		APPROVED LAND P.A. 345 OF Baraga Cou	1990	MICHAEL D. * MILESKI PROFESSIONAL SURVEYOR
			applied in restoring or ree	•	AOFESSION
J-15,	•	•		•	
	having no identif feet). Found no	iable marks is locat evidence of the ot	ed at record U.S. be	aring and distance nor of Mr. Thom	ow birch stump 17" in di (N42°W 39 lks = 25.7 pson's new bearing tree the original corner.
C. Descripti	ion of monument for c	orner and accessories	established to perpetuate	locating the position o	f the corner:
J-13;	South One-quarte	er Corner Section 3	5, T51N, R31W, on §	5th Correction Line.	,
	Replaced found appropriately star	iron pipe with a mped as to location	1" (I.D.) x 36" ga	alvanized iron pipe	with 2" aluminum c
	Set 60d spike Set 60d spike Set 60d spike Set 60d spike	SW/side 1 S/side 1	3" Sugar Maple 5 4" Sugar Maple 5	N19°E 15.78 503°W 18.23 585°W 28.03 N47°W 31.78	2' 3'
		new bearing trees n	narked with upper ar	nd lower face blaze	s and scribed "NBT".
Signed by Surveyor's M	ichigan License No		LIBER 4 PAGE 51	_	STATE BOARS OF LANS SURVEYORS, JAM. 28, 19 REVISEO MAY 14, 19 REVISEO JAM., 19

A. Description of original monument and accessories and/or subsequent restoration:

J-13; South One-quarter Corner Section 35, T51N, R31W, on 5th Correction Line.

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Sugar 12 N55°E 34 lks. (Gone)

and a

Birch 12 N42°W 39 lks. (Recovered as a 17" dia. severely decayed stump having no identifiable marks.)

According to his field notes dated 12 November 1943 (copies of which were obtained at Northern Hardwoods' office in L'Anse) the late Norman Thompson, RLS # 4348 recovered the birch U.S. bearing tree and remonumented the corner with a cedar post. Mr. Thompson noted the following new bearing trees:

White Pine 9 S02°W 24.6' (Gone) and a Hemlock 2 S34°E 3.0' (Gone)