

BERRIEN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

DEC 13 10 50 AM '95

*[Signature]*  
11-22-95  
For corners in  
BERRIEN  
(County)

*[Signature]*  
REGISTER OF DEEDS  
BERRIEN COUNTY MICHIGAN

	Located In:	Corner Code #
1. Public Land Survey	T <u>7</u> S R <u>17</u> W	<u>M-9</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Robert W. Prestine, in a field survey on November 28, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

M-9 Southeast Corner Section 24, T. 7 S., R. 17 W.  
Govt.  
Sugar 20" S 24½ W 13  
Beech 24" N 33 W 50

12/13/95 111#2978 A66  
CORNER \$7.00  
12/13/95 111#2978 A66  
STATE REMON FEE \$2.00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-9  
Found 3/4" pipe in monument box  
Set by M.D.O.T. 1971

*[Signature]*  
MAR 27 1996  
COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9  
Set 3/4" x 15" iron & remon cap over stone in monument box  
Center 8" Spruce N 36° E 72.8'  
S 60° E 90.14' NW corner of Hanger  
South 42.95 NE corner of Hanger  
N 46° W 116.92' SE corner Brick bldg. (Old School)  
Cass County corner in South 7.8' Govt. jog 8.58'

This position is accepted as a careful and faithful reestablishment of the position of the original corner.



Signed by Robert W. Prestine Date December 11, 1995

Surveyor's Michigan License No. 18662