

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1996 DEC 18 AM 11:17

For corners in

DICKINSON

(County)

Located In:

Corner Code #

WAUCEDAH TWP.

1. Public Land Survey T 40N R 28W
- T    R
- T    R
- T    R
2. Property Controlling S    T    R
- in Section S    T    R
3. Miscellaneous S    T    R
- Property in Section S    T    R

M-1  
K-1

REGISTER OF DEEDS  
DICKINSON COUNTY  
IRON MOUNTAIN, MI 49801

21

Register of Deeds Stamp & File Number

4. Lot No.           , Recorded Plat
5. Private Claims

I, ROBERT F. PERKINS, in a field survey on 10-15, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-1 NORTHEAST CORNER SECTION 1,  
T40N-R28W (CLOSING CORNER)  
POST BY J. H. MULLETT, D.S. 1848  
ORIGINAL BEARING TREES  
CEDAR 12" S55°E 12 L.  
CEDAR 15" S79°W 23 L.

K-1 NORTHWEST CORNER SECTION 1,  
T40N-R28W (CLOSING CORNER)  
POST BY J. H. MULLETT, D.S. 1849  
ORIGINAL BEARING TREES  
HEMLOCK 10" S48°W 19 L.  
SUGAR 14" S25°E 30 L.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-1 FOUND 4" SCRIBED CEDAR POST.  
ALSO FOUND POINT OF SMALLER  
OLDER POST ALONG SIDE (POSSIBLE  
ORIGINAL).  
FOUND CEDAR 11" SCRIBED "B.T."

K-1 NO EVIDENCE OF ORIGINAL CORNER  
OR ACCESSORIES FOUND.  
PLACED CORNER ON 4TH. CORRECTION  
LINE AT PROJECTION OF ANCIENT  
FENCE LINE SOUTH, 1016' EAST OF  
STANDARD CORNER TO WEST (GLO  
DISTANCE IS 1023').  
THE ABOVE LOCATION FALLS  
APPROXIMATELY IN OLD EAST-WEST  
FENCE LINE.  
ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON

12-17-96  
RFP

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-1 SET 3 1/4" STAMPED D.C. REMON.  
CORNER ON 4TH CORRECTION LINE  
2.30' NORTH OF ABOVE FOUND POST.  
NEW BEARING TREES:  
CEDAR 6" N58°W (M.B.) 7.22' NAIL/TAG  
CEDAR 9" N27°E (M.B.) 23.55' NAIL/TAG  
CEDAR 6" S45°E (M.B.) 13.73' NAIL/TAG  
CEDAR 11" S31°W (M.B.) 8.15' EXISTING B.T.  
PLACED CARSONITE STAKE 0.5' NORTH OF CORNER.

K-1 SET 3/4" STAMPED D.C. REMON. CORNER  
AT ABOVE DEESCRIBED LOCATION.  
NEW BEARING TREES:  
HEMLOCK 24" S67°W (M.B.) 109.30' NAIL/TAG  
MAPLE 40" S46°W (M.B.) 111.62' NAIL/TAG  
MAPLE 16" S52°W (M.B.) 151.14' NAIL/TAG  
W. PINE 10" S12°W (M.B.) 89.11' NAIL/TAG  
PLACED CARSONITE MARKER 1.0' EAST.

Signed by

*Robert F. Perkins*

Date

NOVEMBER 6, 1996

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1990  
REVISED MAY 1995  
REVISION 1993

