## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #								
(County)	-									
IORWAY TOWNSHIP										
. Public Land Survey	TŘ		1							
	<u>T</u>									
Donate Controlli	TR									
Property Controlling	S 35 T 40N R 29W S 35 T 40N R 29W	09 10	ĺ							
n Section	S T R	IU								
i. Miscellaneous	s T B	177								
Property in Sec.	S T R	····								
• •			) P	egister (	of Deed	ls Stan	np & F	ile Numl	oer	
	corded Plat		A	вс	D E	F G	Н	l J	ĸ I	. м
i. Private Claims			2		ŢŢ	ŢĪ	Ţ	ΠŢ		
	9/09/20	14	3 C		Î	i	_ ;		1-1	i
Jeremy J. Pipp , in	n a field survey on 9/09/20	14 do hereby state	<u> </u>				Ţ	1	17	
hat under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2										
bove were in conformance with regulations and rules therefore as required in the current manual of survey 5										
astructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 15 14 15								3		
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 he rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 24										
e-established, monumented, recove	, , ,	i I	ï	1	 	1-13-	1-2	1		
			10-						+	
Not more than 2 corners, all in the same town and range, may be recorded					1	-28	—27 	26-	13	5— 
on this certificate.							34	1		

- $oldsymbol{\lambda}$ . Description of original monument and accessories and/or subsequent restoration:
- (09) Center-East One-Sixteenth corner of Section 35. Not set in original survey, no evidence of subsequent establishment.
- (10) South One-Sixteenth corner common to Sections 34 and 35. Not set in original survey. Found Fence corner, with fence lines running North and East from said corner.
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 35.
- (10) Corner position established mid-point and on-line between the West One-Quarter corner and the Southwest corner of Section 35. Found Fence Corner is  $\pm$ 1-15 feet East of this position.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(09)	DNR monument	(10) i	DNR monument						
10" Maple	N16E 7.25' (1/16S,BT)	4" Cedar	N81E 3.51' (1/16S,BT)						
9" Maple	\$63E 12.62' (1/16\$,BT)	8" Cedar	S20E 7.84' (1/16S,BT)						
6" Maple	S31W 12.20' (1/16S,BT)	5" Cedar	S75W 7.59' (1/16S,BT)						
6" Maple	N44W 9.87' (1/16S,BT)	5" Cedar	N33W 3.37' (1/16S,BT)						
All trees a	are blazed, scribed, and	All trees as	All trees man blazed, scribed, and						
painted. N	Measurements are to nail in	paints OF	Sy ments are to nail in						
side of tre	ee, bearings are magnetic.	sige of tree	, bear ogs are magnetic.						

For the Michigan Department of Natural Resources in orest Rabbi

September 10, 2014

N STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Surveyor's Michigan License No.

PROFESSIONAL Parest RiskRME YOUR ion

20455

FOR**5.044**70VED BY

Rervised Oct., 1995